

ATOMIC ENERGY COMMISSION CO I

FEB 2 7 1971

J. B. Henderson, Chief, Reactor Construction Branch, CO

JERSEY CENTRAL POWER AND LIGHT COMPANY, FORKED RIVER 1, DOCKET NO. 50-363

The enclosed report of the management interview, conducted January 4, 1971, with the subject applicant, discusses the findings of the initial quality assurance inspection of the subject project.

The applicant was receptive and stated corrective action would be taken on each item discussed.

Compliance will conduct a follow-up inspection in the near future to examine the corrective action taken.

Liederbach, Nuclear Quality

Hederbont

Assurance Engineer Division of Compliance

Enclosure: CO Report No. 363/71/1

cc:w/enclosure

E. G. Case, DRS(3)

P. A. Morris, DRL

R. S. Boyd, DRL(2)

R. C. DeYoung, DRL(2)

D. J. Skovholt, DRL(3)

P. W. Howe, DRL(2)

A. Giambusso, CO

L. Kornblith, Jr., CO

R. H. Engelken, CO

Regional Directors, CO

REG Files