



UNITED STATES
ATOMIC ENERGY COMMISSION
WASHINGTON, D.C. 20545

JAN 19 1971

J. B. Henderson, Chief
Reactor Construction Branch
Division of Compliance

JERSEY CENTRAL POWER AND LIGHT COMPANY (FORKED RIVER NO. 1)
DOCKET NO. 50-363

The enclosed report of the initial quality assurance inspection of the subject facility is transmitted for information and possible action.

This inspection was performed earlier in the licensing review stage than other similar inspections in the recent past.

Compliance found that the applicant has developed a quality assurance program which is consistent with commitments in the PSAR. Three areas, however, need further attention:

1. Policy and procedures for design control (Criterion III).
2. Policy and procedures related to applicant review of procurement documents (Criteria II and IV).
3. Policy and procedures relative to the applicant's internal audit and schedules for audit of contractor activities (Criterion XVIII).

These findings were discussed with the applicant in a meeting on January 4, 1971. The results of that meeting will be discussed in a report now in preparation.

F. J. Liederbach
F. J. Liederbach, Nuclear Quality
Assurance Engineer
Division of Compliance

Enclosure:
CO Rpt No. 363/70-2

cc w/enclosure:
E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)

P. W. Howe, DRL (2)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
Regional Directors, CO
E. M. Howard, CO:I
REG Central Files

B/428