50-219

AUG 281974

Memo to File

TELEPHONE CALL FROM MS. JUDY RUSSELL, NEW YORK DAILY NEWS

A telephone call was received from Ms. Judy Russell of the Freehold ##
Bureau of the New York Daily News on August 27, 1974. Specifically
Ms. Russell had questions pertaining to the February/March 1973 report
documenting our inspection of Oyster Creek (Report No. 50-219/73-03).
Mr. Peter Knapp took the call and upon the advice of Mr. O'Reilly this
matter was referred to the Public Information Office at Headquarters.
On August 27, I contacted Mr. Carl Gustin at Headquarters and informed
him of the telephone call. Mr. Gustin contacted Ms. Russell and then
recontacted this inspector. Mr. Gustin stated that Ms. Russell had
some very specific questions dealing with the inspection report noted
and suggested that I contact Ms. Russell directly. Mr. Gustin stated
that his preliminary evaluation of the contact did not indicate any
abnormal or antagonistic approach on the part of Ms. Russell.

At approximately 3:00 p.m. on August 27th I recontacted Ms. Russell directly at which time she had several questions pertaining to the aforementioned inspection report. She was primarily interested in the corrective action taken by the licensee to which I answered that these items had been corrected and were documented in inspection report (50-219/73-16). She continued further with questions concerning statements made by this inspector as part of his evaluation conducted at that time. Primarily she was interested in whether the attitude of Jersey Central had changed any from the "utter disregard for marina owners problems". I stated that the attitude of the licensee had changed considerably and that when viewed in light of the still "adversary" attitude of the marina owners, was considered more than acceptable. I stated that the licensee was making every effort to be helpful when approached with specific problems by the marina owners.

Ms. Russell then asked some further questions relating specifically to the final environmental statement for the Forked River Plant. These questions dealt with cooling water blowdown problems as well as salt drift and she also discussed various problems relating to the soaping of the discharge canal from Oyster Creek. I stated that Licensing was reviewing all environmental aspects of the combined site (Oyster Creek and Forked River) and that any decision made on environmental corrective actions would be based upon this detail review.

8475

Ms. Russell had some further questions pertaining to our inspection program in the environmental area and have reviewed this program briefly with her stating that routine inspections are made of environmental monitoring at our facilities and that these inspections included the verification of the licensee's analytical capability on a routine basis based on the split samples with the facility, the AEC and the State of New Jersey.

Ms. Russell then summarized her impressions to me at the conclusion of this telephone conversation and based on this summary no misunderstandings or misrepresentations were identified on the part of this inspector.

Dr. Charles O. Gallina Radiation Specialist

cc: K. Abraham

J. P. Stohr

E. Greenman

yellowst-R

MEMO ROUTE SLIP Form AEC-93 (Rev. May 14, 1947) AECM 0240			See me about this.  Note and return.	For concurrence.	For action.	
TO (Name and unit)  K. Seyfrit  RO: HQ		INITIALS	Attached is statistical information on the switch			
		DATE	drift problem at the Oyster Creek Facility. I'd hope herein will assist to get the licensee and			
ce: H. D. Thornburg RO:HQ		INITIALS	Regulatory each to work toward resolution.			
		DATE				
TO (Name and unit)		INITIALS	REMARKS			
		DATE				
FROM (Name and unit)  E. J. Brunner, Chief Reactor Operations Branch RO: I		REMARKS				
PHONE NO. 8-337-1246	8/27					

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO: 1971 O - 445-469

Memo to File

gac 8/9/74

1 .

Thru: D. L. Caphton, Senior Reactor Inspector

OYSTER CREEK (DN 50-219) ABNORMAL OCCURRENCE FREQUENCY

On August 6, 1974, I called Don A. Ross (JCP&L) to express concern about the excessive number of AO's experienced in 1974 at Oyster Creek (44 to date). Mr. Ross informed me that with respect to setpoint drift he will give this matter top priority effort at his level of management, to move from dead center towards resolution.

For the year to date statistical information is as follows:

- (1) 24% of the AO's are attributed to Main Steam line low pressure switch setpoint draft (increased surveillance frequency).
- (2) 11% of the AO's are attributed to seismic shock suppressor failures.
- (3) 14% of the AO's are attributed to other setpoint repeatability difficulties.
- (4) 11% of the AO's are attributed to vacuum break problems (increased surveillance frequency).
- (5) 40% and the remainder are attributed to other problems.

The 70% figure related to setpoint drift was referenced and acknowledged by Mr. Ross. The conversation was cordial and Mr. Ross indicated his best efforts would be directed toward resolution.

Edward G. Greenman Reactor Inspector

Edward J. Deamer

cc:

D. L. Caphton

E. J. Brunner

J. P. O'Reilly

E. McCabe

83/4/84119 (p)