

Appendix

NOTICE OF VIOLATION

Consumers Power Company

Docket No. 50-255

As a result of the inspection conducted on November 26, 1984 through January 4, 1985 and in accordance with the General Policy and Procedures for NRC Enforcement Actions (10 CFR Part 2, Appendix C), the following violation was identified:

Technical Specification 2.3, Table 2.3.1 states that a low flow trip setpoint of greater than or equal to 95% of full flow is required for four primary coolant pump operation and a setpoint of greater than or equal to 71% is required for three pump operation.

Contrary to the above:

- a. For the time of operation during July through September 1984, all four channels of four pump low flow trip were found to be less than the required 95% setpoint. (The greatest calculated error was 0.63%.)
- b. For an indeterminate period of time, possibly since plant startup, the three pump low flow trip was set less than the required 71% setpoint. (The greatest calculated error was 2.9%.)

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

JUN 21 1985

Dated _____

C. E. Norelius

C. E. Norelius, Director
Division of Reactor Projects

8502210322 850131
PDR ADDOCK 05000255
Q PDR