

P. O. Box 165, New Hill, North Carolina 27562 January 23, 1985

FILE: SH N-2/18 Item 189 MQAH 85-32

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1
DOCKET NO. 50-400
INSTRUMENTATION INSTALLATION - PROCESS CONTROLS

Dear Mr. O'Reilly:

This is to confirm the January 22, 1985 telephone conversation between Mr. N. J. Chiangi (CP&L) and Mr. A. Hardin. Mr. Hardin was informed that the October 12, 1984 potentially reportable item, pertaining to inadequate process controls for instrumentation installations, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e).

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. R. C. DeYoung

Mr. G. Maxwell

Mr. R. L. Prevatte

N. J. Chilangi - Manager

Quality Assurance/Quality Control

Harris Plant

8502210367 850123 PDR ADOCK 05000400 PDR OFFICIAL COPY