

DEC 22 1971

P. T. Carlson, Acting Chief, Reactor Testing & Operations Br.
Division of Compliance, HQ

CO INSPECTION REPORT NO. 50-219/71-05
JERSEY CENTRAL POWER AND LIGHT COMPANY
OYSTER CREEK 1 - DWR

The subject inspection report is forwarded for your information.

The actions taken by JCP&L are considered appropriate with respect to the failures discussed in the subject report. We continue to have concerns relative to the absence of check valves for the instrument air lines, the existing instrument air system surveillance program, and the long range adequacy of the main steam isolation valve hydraulic cylinder "cushion spuds". These matters will be given additional consideration during future inspections.

G. L. Madsen
Acting Sr. Reactor Inspector

Enclosure:
Subject Inspection Report

cc: E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRS (2)
A. Giambusso, CO
L. Kornblith, CO
R. H. Engelken, CO
Regional Directors, CO
CO Files
DR Central Files

OFFICE ▶	CO				
SURNAME ▶	<i>GLM</i> Madsen:smg				
DATE ▶	12/21/71				