

Southern California Edison Company


SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

RECEIVED
NRC

1985 FEB 11 AM 11:10



REGION V

J. G. HAYNES
STATION MANAGER

TELEPHONE
(714) 492-7700

February 5, 1985

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Subject: Docket Nos. 50-361 and 50-362
Prompt Report
License Conditions 2.C.(14)a and 2.C.(12)a
San Onofre Nuclear Generating Station, Units 2 and 3

This submittal provides written confirmation of our prompt notification of February 5, 1985, pursuant to License Condition 2.G to Facility Operating Licenses NPF-10 and NPF-15 for San Onofre Units 2 and 3, respectively, of reportable occurrences associated with the fire protection program.

License Conditions 2.C.(14)a and 2.C.(12)a of Operating Licenses NPF-10 and NPF-15, respectively, require that SCE maintain in effect and fully implement the Fire Protection Plan as delineated in the Fire Hazards Analysis (FHA).

During the current Unit 2 refueling outage, the routine 18-month surveillances of over 2,000 fire rated assemblies and other fire protection systems have been conducted. Approximately 8% of these surveillances identified deficiencies including missing or damaged penetration seals, seal shrinkage, and damaged cable wraps. In accordance with Technical Specification 3.7.9, a compensatory fire watch was established within one hour of discovery of each discrepancy during the surveillance. In addition, Nonconformance Reports (NCR's), documenting these deficiencies, have been issued.

Our surveillance of fire rated assemblies is continuing and appropriate corrective action is being taken or is being evaluated and will be implemented as part of the dispositioning of all NCR's. The cause and corrective actions implemented will be reported in the Licensee Event Report and 14-Day Follow-Up Report by February 19, 1985.

If you require additional information regarding the above, please so advise.

Sincerely,

J.G. Haynes/dem

8502250342 850205
PDR ADOCK 05000361
S PDR

10

IE-18

Mr. J. B. Martin

- 2 -

February 5, 1985

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U. S. Nuclear Regulatory Commission, Document Control Desk

Institute of Nuclear Power Operations (INPO)