


Public Service Company of Colorado

16805 WCR 19 1/2, Platteville, Colorado 80651



10

Regional Administrator ATTN: Mr. E. H. Johnson U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011

DOCKET NO. 50-267

SUBJECT: Segment 3 Fuel Element Inspection Program

REFERENCE: P-85011, Gahm To Johnson, Dated January 17, 1985

Dear Mr. Johnson:

In the referenced letter (P-85011) paragraph five read as follows:

"When spent fuel shipping resumes, spent fuel from Regions, 13, 22, and 33 will be shipped. Of these three regions, only Regions 29 and 22 remain to be photographed during spent fuel shipping."

This paragraph should read as follows:

"When spent fuel shipping resumes, spent fuel from Regions 13, 22, and 33 will be shipped. Of these three regions, only Regions 13 and 22 remain to be photographed during spent fuel shipping."

Please make note of the corrected region number (underlined).

If you have further questions on this matter, please contact Mr. Frank Novachek of my staff at (303) 785-2224, Ext. 201.

Sincerely yours.

affulle for

RETURN ORIGINAL RETURN RIV FU RIV J. W. Gahm Manager, Nuclear Production

8502250696 850 PDR ADOCK 050

JWG/djm