FEB 11 1985

Docket Nos. 50-272 50-311

Public Service Electric and Gas Company ATTN: Mr. Richard A. Uderitz Vice President - Nuclear P. O. Box 236 Hancock's Bridge, New Jersey 08038

Gentlemen:

Subject: Inspection No. 50-311/84-45

This refers to the routine safety inspection conducted by Mr. R. A. McBrearty of this office on December 10-21, 1984, at Salem Nuclear Power Station, Unit 2 of activities authorized by NRC License No. DPR-75 and to the discussions of our findings held by Mr. McBrearty with Mr. J. M. Zupko, Jr., at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Siginal Signed By:

Stewart D. Ebneter, Director Division of Reactor Safety and Safeguards

Enclosure: NRC Region I Inspection Report No. 50-311/84-45

cc w/encl: R. L. Mittl, General Manager - Nuclear Assurance and Regulation J. M. Zupko, Jr., General Manager - Salem Operations E. A. Liden, Manager - Nuclear Licensing and Regulation C. P. Johnson, Manager - Quality Assurance Nuclear Operations P. M. Krishna, Manager - Nuclear Review Board M. J. Wetterhahn, Esquire

R. Fryling, Jr., Esquire

02250717 8502 ADOCK 0500

CFFICIAL RECORD COPY

DL50-311/84-45 - 0001.0.0 01/30/85

TEOL

Public Document Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center (NSIC) NRC Resident Inspector State of New Jersey

A

bcc w/encl: Region I Docket Room (with concurrences) Senior Operations Officer (w/o encls) DPRP Section Chief

RI:DETP RACH McBrearty/sm 1/31/85





OFFICIAL RECORD COPY

DL50-311/84-45 - 0002.0.0 01/30/85