

APPENDIX A

NOTICE OF VIOLATION

Power Authority of the State of New York  
Indian Point 3 Nuclear Power Plant

Docket No. 50-286  
License No. DPR-64

As a result of the inspection conducted on September 16, 1984 to October 15, 1984, and in accordance with the NRC Enforcement Policy, 10 CFR 2, Appendix C, the following violation was identified:

- A. Indian Point Unit 3 Security Plan, dated May 14, 1982, Section 2.7, Security Procedures, requires the licensee to establish written Security Implementing Procedures.

Security Procedure, SDP 4.1, "Protection of Safeguards Information," requires the licensee to identify unclassified safeguards information and to store such information in steel filing cabinets equipped with a locking bar and GSA approved combination padlock.

Contrary to the above, on September 21, 1984, approximately 30 drawings marked as Safeguards Information, were stored in a steel cabinet which was not equipped with a locking bar and approved padlock.

This is a Severity Level IV Violation (Supplement III).

Pursuant to the provisions of 10 CFR 2.201, the Power Authority of the State of New York, is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8411050455 841031  
PLR ADDCK 05000286  
PDR  
Q