

ENCLOSURE

DESCRIPTION OF VIOLATIONS

Jersey Central Power and Light Company  
Madison Avenue at Punch Bowl Road  
Morristown, New Jersey 07960  
Docket No. 50-219

Based on the results of the NRC inspection conducted on March 18-20, 1975, it appears that certain of your activities were not conducted in full compliance with conditions of your AEC Facility License No. DPR-16 as indicated below:

1. Contrary to Technical Specifications 4.6.B(3), surface water sampled at five locations was not analyzed for U, Ra-226 and Ra-228 between July 2, 1974 and October 22, 1974, an interval exceeding four weeks.

This deficiency was identified by the licensee, but the corrective action appears to be inadequate to prevent recurrence of this item.

2. Contrary to Technical Specifications 4.6.B(3), well water sampled at six locations was not analyzed for U, Ra-226 and Ra-228 between July 5, 1974 and December 19, 1974, an interval exceeding twelve weeks.

This deficiency was identified by the licensee, but the corrective action appears to be inadequate to prevent recurrence of this item.