

~~TOP SECRET - CONFIDENTIAL~~

APPENDIX A

~~SECRET~~
~~CONFIDENTIAL~~
~~TOP SECRET~~
ies
DE

University of California - Santa Barbara
Department of Chemical and Nuclear Engineering
Santa Barbara, California 93106

Docket No. 50-433
License No. R-124

Notice of Violation

Based on the results of the NRC inspection conducted on July 10-12, 1979, it appears that certain of your activities were not in full compliance with applicable NRC regulations and conditions of your license, as indicated below.

1. Section 1.1, Paragraph 7 of the licensee's approved security plan states in part,

[Redacted]

Contrary to the above, the inspectors determined on July 11, 1979, from interviewing police officers and supervisors, that

This is a deficiency.

2. Section 1.2.3. of the licensee's approved security plan states,

[Redacted]

Contrary to the above,

at 1:37 p.m. and 1:47 p.m. on July 11, 1979.

This is an infraction.

3. The licensee's approved security plan, Paragraph 1.1 states in part,

8502260236 840822
PDR FOIA
AFTERG084-284 PDR

~~TOP SECRET~~

Contrary to the above, at the nuclear reactor facility on June 8, 1979 at 7:04 p.m. and on July 11, 1979 at 2:00 p.m. and were made.

This is a deficiency.

4. The licensee's approved security plan, Paragraph 1.2.2 states in part,

Contrary to the above, the inspectors determined by examining the and that on several dates including October 13, 1978 and April 21, 1979, the licensee omitted on those dates. On those dates,

This is a deficiency.

5. Paragraph 1.2.1 of the licensee's approved security plan states in part,

Paragraph 2.2 of the licensee's approved security plan states in part,

Contrary to the above, the inspectors observed that the effectiveness of the

This is an infraction.

6. The licensee's approved security plan, Paragraph 1.2.3 states in part,

Contrary to the above, the inspectors observed on July 11, 1979 numerous items of equipment (storage cabinet, 55-gallon drums, etc)

This is a deficiency.