UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

ATOMIC SAFETY AND LICENSING BOARD

Before Administrative Judges:

Dr. George A. Ferguson
Dr. Peter A. Morris

DOCKETED

*84 NOV -7 A10:20

Docker of acong the

SERVED NOV 7 1984

In the Matter of

LONG ISLAND LIGHTING COMPANY

(Shoreham Nuclear Power Station, Unit 1) Docket No. 50-322-OL

November 6, 1984

ORDER CORRECTING TRANSCRIPTS OF SEPTEMBER 26 THROUGH OCTOBER 4, 1984

The November 5, 1984 errata to the transcripts of September 26 through October 4, 1984, filed jointly by the parties, as modified by the listing attached to this order, is hereby approved. Proposed errata which have been modified or deleted by the Board are denoted by asterisks or line-outs, respectively.

The proposed errata to Mr. Eley's answer at Tr. 24,113/1, which oddly included a question mark, is not approved. It should be verified by Counsel for Suffolk County after checking with its witness.

8411070233 841106 PDR ADDCK 05000322 PDR PDR

DSOF

Steps are being taken to arrange for the court reporting firm to issue corrected transcript pages to the recipients of the transcripts.

IT IS SO ORDERED.

FOR THE ATOMIC SAFETY AND LICENSING BOARD

Lawrence Brenner, Chairman ADMINISTRATIVE JUDGE

Bethesda, Maryland November 6, 1984

Attachment: Modified errata listing to transcripts of September 26 through October 4, 1984.

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION BEFORE THE ATOMIC SAFETY & LICENSING BOARD

In the Matter of:

SHOREHAM NUCLEAR POWER STATION : Docket No. 50-322-OL

Long Island Lighting Company

JOINT ERRATA OF LILCO, SUFFOLK COUNTY AND NRC STAFF TO TRANSCRIPT OF Monday, September 26, 1984

Page/Line	Reads	Should Read
23572/20 *23576/6 23625/19 23646/17 23676/19	Trans-American you anything now as Schwanger	Transamerica you have anything know of Swanger

Monday, October 1, 1984

Page/Line	Reads	Should Read
*23751/12 16 23778/21 23784/14 23805/2 23830/3 23830/22 23833/7 *23845	Ellis to DDI P-29-7 possible metalurgy that doing it This page is a duplicate of	Dynner of TDI P-29-27 possibly metallurgy that was doing it f 23846, and should be struck.

Tuesday, October 2, 1984

Page/Line	Reads	Should Read
22052/4	DARLA TARLETS	DAVID DREIFUS
23853/4	the	to
23856/15 23859/23	to	you
	1940	1949
23863/1	any	either
23864/14	A	0
23868/13 23869/12	improvements	Improvement
23869/19	almond	Almen
23871/10	while	well
23873/5	that	then
23875/7	Scheid	Scheidt
23891/2	ration	ratio
*23914/18	arrhenius	Arrhenius
23914/10	question	quest log
23932/7	- vouldd	would-
23956/10	represented	represented to
23961/18	Piersgills	Pickersgill
23963/10	Salzer	Sulzer
	force	forced
23965/13	resting	reasonancel
23965/21	force	forced
23967/6 23971/14	Beaubaker	Bob Ecker
239/1/14	Beaubaker	BOD SCREE
22973/17-21	moved to strike	motion granted but Judge
		Brenner indicated it would stay in transcript and he would indicate what portion will be disregarded - see
23974/3	necessitate in	necessitate
*23981/25	Strike entire line, same line	
	of next page.	is repeated as beginning
23993/1	"Lands"	Lambs
24006/23	MCR	Maximum Continuous Rating
24009/22	Ehnibit	Exhibit
24010/20	filed	failed
24014/4	continued	completed
24014/10	that	what
24014/24	light	Lloyd's
24016/12	Chrankshafts	Crankshafts
24018/18	generates a set	generator set
24018/23	bad	but
24020/3	by	my
24040/6	diforged	dieforged
24040/14	3400	3500
24057/2	CIMAK	CIMAC
24058/5	CIMAK	CIMAC
24058/12	CIMAK	CIMAC
24059/5	CIMAK	CIMAC
24059/8	CIMAK	CIMAC
24059/13	CIMAK	CIMAC
24059/16	CIMAK .	CIMAC

-2-

Wednesday, October 3, 1984

24126	4247
24063/24 24106 2	
74003/74 F1100	udge Brenner
24003/13	oncerning
240/5/10	as
240/0/3	hat
24003/14	particular
24000, 27	inderstand
24080/20	excised
2400//24	competent
24034, 10 competer	marine and
24033/1/ marine	iving the
24030/3	nedalist
24100/3	forced
24100/3	3 x 11?
F47731 4 72 "	
24110/1/	0
24124/0	ralue delete "oil"
21230/3	
21210/2	io io
24131/3	100
2413//12	finished
24103/3	find
21103/0	rely on or
24170/20 indicated	indicator
24172/20-21 Some words appear to be mi	ssing.
24173/12 46084.5	608.5
24175/8 load n	ote
24175/18 wt W	hat
24177/1 load	tote
24177/4 load	note
24179/7 what	delete first "what"
24185/4 exclusively	explicitly
24185/10 that	it
24191/22 the factor that was safety	the factor of safety
	calculated by
	ashore
	fatigue
	JUDGE MORRIS
6 T 6 6 U / 2 J	Keine
21220/21	
*24244/25 weight	wave ,
1	,

Thursday, October 4, 1984

Page/Line	Reads	Should Read
24254/1 24259/11 24264/15 24264/18 24265/22 24265/22 24266/1 24271/24 24308/8	treasuer ressure-volume improved accrued and figure 7.078 prefile an	treasurer pressure-volume approved approved than forging 7,078 prefiled on
24342/7	under	understand