

FEB 14 1985

Docket No. 50-440
Docket No. 50-441

The Cleveland Electric Illuminating
Company
ATTN: Mr. Murray R. Edelman
Vice President
Nuclear Group
Post Office Box 5000
Cleveland, OH 44101

Gentlemen:

Thank you for your letter dated January 31, 1985, informing us of the steps you are taking to correct the emergency preparedness exercise weaknesses that were identified in Inspection Report Nos. 50-440/84-24 and 50-441/84-22 and our letter dated December 19, 1984.

Your response to weaknesses 1-4 and 6-7 were acceptable; however, we are still concerned regarding the lack of consistency between your protective action recommendations and the subareas used by the State of Ohio and counties. We feel that plans of the licensee, State, and local governments should not be in isolation from one another with regard to protective action formulation, rather, an integrated approach is most likely to provide the best response. Consistency in protective action recommendation formulation is an item which will be examined during our upcoming Emergency Preparedness Implementation Appraisal. However, we urge that you reconsider your response to weakness No. 5 to ensure that consistent protective action recommendations will be made.

Sincerely,

C. J. Paperiello
C. J. Paperiello, Chief
Emergency Preparedness and
Radiological Protection Branch

cc: Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health
W. Weaver, FEMA, Region V

cc w/ltr dtd 01/31/85:
J. Waldron, Manager, Plant
Technical Department
M. Lister, Manager of Plant
Operations
L. Beck, General Supervisor
Licensing and Fuels Management
DMB/Document Control Desk (RIDS)
Terry J. Lodge, Esq.
D. Matthews, EPB, OIE

IE35
1/1

8502270079 850214
PDR ADCK 05000440
Q PDR

RIII
WGS
Snell/Id
02/13/85

RIII
Philips
Philips

RIII
RCK
Knop

RIII
Paperiello
2/19/85