SAFEGUARDS INFORMATION

FFB 2.2 1985

Carolina Power and Light Company ATTN: Mr. E. E. Utley Executive Vice President Power Supply and Engineering and Construction

411 Fayetteville Street Raleigh, NC 27602

Gentlemen:

SUBJECT: REPORT NO. 50-261/85-10

On February 4-8, 1985, NRC inspected activities authorized by NRC Operating License No. DPR-23 for your H. B. Robinson Unit 2 facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790(d) and 10 CFR 73.21, safeguards activities and security measures are exempt from public disclosure; therefore, the enclosures to this letter, with the exception of the report cover page which presents a nonexempt summary, will not be placed in NRC's Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely.

David M. Verrelli, Chief Reactor Projects Branch 1 Division of Reactor Projects

Enclosure: Inspection Report No. 50-261/85-10 (Safeguards Information)

cc w/encl: G. P. Beatty, Jr., Manager Robinson Nuclear Project Department R. E. Morgan, Plant General Manager

bcc w/encl: (See page 2)

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION. UPON SEPARATION THIS

PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION

8502280078 850 PDR ADDCK 050

WARNING UNAUTHORIZED DISCLOSURE IS SUBJECT TO ADMINISTRATIVE AND CRIMINAL PENALTIES.

SAFEGUARDS INFORMATION

Carolina Power and Light Company

2

FEB 22 1985

bcc w/encl: IE File NMSS/SGPL NRR/DL/SSPB

bcc w/Inspection Summary: Document Control Desk, 016 NRC Resident Inspector State of South Carolina

DMoore:cdg 02/10/85 DMcGuire 02/20/85

KBarr 02/20/85 UStohr 024//85 RII AHardin 02/12/85

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.