



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

APR 26 1996

TU Electric
ATTN: C. L. Terry, Group Vice President
Nuclear Production
Energy Plaza
1601 Bryan Street, 12th Floor
Dallas, Texas 75201-3411

SUBJECT: NRC INSPECTION REPORT 50-445/96-04; 50-446/96-04 AND NOTICE OF VIOLATION

This refers to the inspection conducted by A. T. Gody, Jr., H. A. Freeman, and V. L. Ordaz-Purkey of this office on February 18 through March 30, 1996, at the Comanche Peak Steam Electric Station, Units 1 and 2, facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, the NRC has determined that one violation of NRC requirements occurred. This violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding the violation are described in detail in the subject inspection report. The violation is of concern because it reflects a negative trend in procedural adherence. These four licensee-identified or self-revealing examples are being cited because they are indicative of the apparent degradation in compliance with equipment control procedures at the facility. In addition, this and other recent inspection reports detail other examples of personnel errors that resulted in events and conditions. Your corrective actions in response to this violation should be sufficiently broad to address this apparent negative human performance trend.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be placed in the NRC


9605010014 960426
PDR ADOCK 05000445
Q PDR

Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



J. E. Dyer, Director
Division of Reactor Projects

Dockets: 50-445
50-446
Licenses: NPF-87
NPF-89

Enclosures:
1. Notice of Violation
2. NRC Inspection Report
50-445/96-04; 50-446/96-04

cc w/enclosures:
TU Electric
ATTN: Roger D. Walker, Manager of
Regulatory Affairs for Nuclear
Engineering Organization
Energy Plaza
1601 Bryan Street, 12th Floor
Dallas, Texas 75201-3411

Juanita Ellis
President - CASE
1426 South Polk Street
Dallas, Texas 75224

TU Electric
Bethesda Licensing
3 Metro Center, Suite 610
Bethesda, Maryland 20814

Morgan, Lewis & Bockius
ATTN: George L. Edgar, Esq.
1800 M. Street, NW
Washington, D.C. 20036

Texas Department of Licensing & Regulation
ATTN: G. R. Bynog, Program Manager/
Chief Inspector
Boiler Division
P.O. Box 12157, Capitol Station
Austin, Texas 78711

Honorable Dale McPherson
County Judge
P.O. Box 851
Glen Rose, Texas 76043

Texas Radiation Control Program Director
1100 West 49th Street
Austin, Texas 78756

Office of the Governor
ATTN: Susan Rieff, Director
Environmental Policy
P.O. Box 12428
Austin, Texas 78711

APR 26 1996

TU Electric

-4-

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)
E-Mail report to M. Davis (MJD1)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan
DRP Director
Branch Chief (DRP/B)
Project Engineer (DRP/B)
Branch Chief (DRP/TSS)

Resident Inspector (2)
DRS-PSB
MIS System
RIV File
Leah Trempier (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:_CP\CP604RP.ATG

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

SRI		AC:DRP/B	D:DRP				
ATGody		WDJohnson	JEDyer				
04/16/96		04/16/96	04/20/96				

OFFICIAL RECORD COPY

APR 26 1996

TU Electric

-4-

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)
E-Mail report to M. Davis (MJD1)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan
DRP Director
Branch Chief (DRP/B)
Project Engineer (DRP/B)
Branch Chief (DRP/TSS)

Resident Inspector (2)
DRS-PSB
MIS System
RIV File
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:_CP\CP604RP.ATG

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

SRI		AC:DRP/B	D:DRP				
ATGod		WDJohnson	JEDye				
04/16		04/16/96	04/20/96				

OFFICIAL RECORD COPY

300010

41