

APPENDIX A

NOTICE OF VIOLATION

Power Authority of the State of New York
Indian Point 3 Nuclear Power Plant

Docket No. 50-286
License No. DPR-64

As a result of the inspection conducted on August 1 - September 15, 1984, and in accordance with the NRC Enforcement Policy, 10 CFR 2, Appendix C, the following violation was identified:

- A. Technical Specification 6.8.1 requires that written procedures covering the applicable activities in Appendix A of Regulatory Guide 1.33, November, 1972, be established, implemented, and maintained.

Contrary to the above, on September 7, 1984, procedures were identified which had not been properly maintained. Specifically, modifications to the battery chargers and batteries had not been incorporated into SOP-EL-2, Revision 3, and SOP-EL-3, Revision 3, and valves 535 and 536 were not listed on the correct motor control centers in COL-EL-1, Revision 2.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, the Power Authority of the State of New York, is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

B411140379 B41108
PDR ADOCK 05000286
G PDR

OFFICIAL RECORD COPY