

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

October 5, 1984

FILE: B09-13510C  
SERIAL: BSEP/84-2107

Mr. R. C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555


BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2  
LICENSE NOS. DPR-71 AND DPR-62  
DOCKET NOS. 50-325 AND 50-324  
MONTHLY OPERATING REPORT

Dear Mr. DeYoung:

In accordance with Technical Specification 6.9.1.6 for the Brunswick Steam Electric Plant, Units 1 and 2, Carolina Power & Light Company herewith submits the report of operating statistics and shutdown experience for the month of September 1984. During a review of the Unit 1 report, it was found that the Gross Thermal Energy Gen. (line 16) is incorrect due to an apparent software problem. This error does not affect other parameters on the report. The problem is being investigated, and a corrected report will be forwarded to you upon its resolution.

Also, based upon a review of outage number 83018 for BSEP Unit 1, the outage type should have been reported as a scheduled (Type S) rather than a forced outage (Type F), as was actually reported. A corrected "Unit Shutdowns and Power Reductions" sheet for the February 1985 report month is attached for your records.

Very truly yours,

  
C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

FH/kal/LETFB1

Enclosures

cc: Ms. J. C. Baker  
Mr. S. W. McDowell  
Mr. J. P. O'Reilly  
INPO

DESIGNATED ORIGINAL  
Certified By MR. Balle 11/07/84

8411140507 841005  
PDR ADOCK 05000324  
R PDR

IE24  
11