

Official

JAN 30 1985

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Executive Vice President
Power Supply and Engineering
and Construction
411 Fayetteville Street
Raleigh, NC 27602

Gentlemen:

SUBJECT: REPORT NO. 50-261/84-52

On December 10 - 14, 1984, the NRC conducted a special inspection of NRC Operating License No. DPR-23 for your Robinson facility dealing with operational readiness following a steam generator replacement outage. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790(a), a copy of this letter and enclosure will be placed in the NRC Public Document Room unless you notify this office by telephone within 10 days of the date of this letter and submit written application to withhold information contained therein within 30 days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original Signed by
Roger D. Walker /for

John A. Olshinski, Director
Division of Reactor Projects

Enclosure:

Inspection Report No. 50-261/84-52

cc w/encl:

G. P. Beatty, Jr., Manager
Robinson Nuclear Project Department
R. E. Morgan, Plant General Manager

bcc w/encl: (See page 2)

8503060464 850130
PDR ADOCK 05000261
G PDR

IEOI

JAN 30 1985

bcc w/encl:
NRC Resident Inspector
Document Control Desk
State of South Carolina

RII

PFredrickson:sa
12/24/84

RII

DMVerrelli
12/24/84