

Duke Power Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MGU1VP)
Huntersville, NC 28078-8985

T. C. McMEEKIN
Vice President
(704) 875-4800
(704) 875-4809 Fax



DUKE POWER

DATE: April 18, 1996

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Subject: McGuire Nuclear Station Unit 1 and 2
Docket No. 50-369

Licensee Event Report 370/96-01, Revision 1
Problem Investigation Process No.: 2-M96-0332

Gentlemen :

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 370/96-01, Revision 1, concerning Unit 2 Refueling Water Storage Tank Level Instrumentation Inoperability during cold weather conditions. This revision is being submitted to include editorial changes to the report. This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (i) and 10 CFR 50.73 (a) (2) (ii). The health and safety of the public was not affected as a result of this event.

Very truly yours,


T.C. McMeekin

JWP/bcb

020201

Attachment

cc: Mr. S.D. Ebnetter
Administrator, Region II
J.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. George Maxwell
NRC Resident Inspector
McGuire Nuclear Station

9605030015 960418
PDR ADOCK 05000370
S PDR

IE22
"

bxc: B.L. Walsh (EC11C)
Zack Taylor (CNS)
G.A. Copp (EC050)
J.I. Glenn (MG02ME)
P.R. Herran (MG01VP)
Cindy Davis (MG01CP)
J.E. Burchfield (ONS Reg Compliance)
G.H. Savage (EC06E)
G.B. Swindlehurst (EC11-0842)
R.F. Cole (EC05N)
J.M. .rye (EC05N)
Tim Becker (PB02L)
P.M. Abraham (EC08I)
R.B. White (MG01VP)
L.V. Wilkie (ON03SR)
D.P. Kimball (CN05SR)
NSRE Support Staff (EC05N)
Kay Crane (MG01RC)
Rich Casler (EC05N)
C.M. Misenheimer (EC08I)