

Arizona Public Service Company

RECEIVED
MTC

1984 NOV -1 AM 11:14

REGION V I&E

October 29, 1984
ANPP-30993-TDS/TRB

50-528

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Reactor Safety and Projects

Subject: Time Extension For Report - DER 84-64
A 50.55(e) Potentially Reportable Deficiency Relating To Pipe
Support Could Not Be Cycled Through Entire Stroke.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between D. Hollenbach and
T. Bradish on September 4, 1984
(B) ANPP-30734, dated October 3, 1984 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
October 30, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by November 15, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

8411160195 841029
PDR ADOCK 05000528
S PDR

11
IE-27

Mr. T. W. Bishop
DER 84-64
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
J. Vorees
J. R. Bynum
J. M. Allen
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
L. Clyde
M. Woods
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339