

Arizona Public Service Company

October 23, 1984  
ANPP-30929-TDS/TRB

U. S. Nuclear Regulatory Commission  
Region V  
Creekside Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director  
Division of Reactor Safety and Projects

Subject: Time Extension For Report - DER 84-63  
A 50.55(e) Potentially Reportable Deficiency Relating To SIT  
Vent Valve Did Not Close During Testing.  
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on  
August 31, 1984  
(B) ANPP-30681, dated September 27, 1984 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in  
Reference (A), and an Interim Report was transmitted by Reference (B).  
At that time, it was estimated that a Final Report would be available by  
October 24, 1984.

Due to the extensive investigation and evaluation required, it is now  
expected that this information will be finalized by November 8, 1984, at  
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Production  
ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

8411160546 841023  
PDR ADDCK 05000528  
S PDR

110  
IE-27

Mr. T. W. Bishop  
DER 84-63  
Page Two

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
D. B. Karner  
W. E. Ide  
D. B. Fasnacht  
A. C. Rogers  
L. A. Souza  
D. E. Fowler  
T. D. Shriver  
C. N. Russo  
J. Vorees  
J. R. Bynum  
J. M. Allen  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
H. D. Foster  
D. R. Hawkinson  
R. P. Zimmerman  
L. Clyde  
M. Woods  
T. J. Bloom

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, GA 30339