

RIVER BEND STATION

POST OFFICE BOX 220 ST FRANCISVILLE LOUISIANA 70775

346-8651

AREA CODE 504 635-6094

February 21, 1985 RBG-20198 File No. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission, Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station - Unit 1 Docket No. 50-458 Interim Report/DR-239

An interim or final status report concerning the wiring of an incorrect isolation signal to two isolation valves supplied by General Electric Company for the Residual Heat Removal System will be provided by February 28, 1985.

Sincerely,

Eddie R Grant for J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

PJD JEB/PJD/trp

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site