

RIVER BEND STATION

POST OFFICE BOX 220

ST FRANCISVILLE, LOUISIANA 70775

346-8651

AREA CODE 504


635-6094

February 20, 1985 RBG-20196 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission, Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station - Unit 1 Docket No. 50-458 Interim Report/DR-247



An interim or final status report concerning the fabrication of pipe anchor clamps will be provided by March 14, 1985.

Sincerely,

for J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

Eddie R Grant

JEB/PJD/trp

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8503080166 850220 PDR ADOCK 05000458 PDR PDR

1/0