

POST OFFICE BOX 2951 - BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

February 22, 1985 RBG-20214 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-278 FEB 27 1985

An interim or final status report concerning the installation of flow switches supplied by Fluid Components, Incorporated in the HVAC System will be provided by March 14, 1985.

Sincerely,

J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing River Bend Nuclear Group

7. 9. England

JEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8503080188 850222 PDR ADOCK 05000458 S PDR IZ-27