



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

December 7, 1984

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Braidwood Station Units 1 and 2
GDC 51 Compliance Review
NRC Docket Nos. 50-456/457

References (a): E. D. Swartz letter to H. R. Denton
dated February 22, 1984

(b): E. D. Swartz letter to H. R. Denton
dated August 9, 1984

Dear Mr. Denton:

References (a) and (b) provided the compliance review against GDC 51 for the reactor containment pressure boundary components of our Braidwood Station. This matter was recently discussed during conference calls with members of your staff on December 3 and 6, 1984. The purpose of this letter is to provide an update of the Reference (b) material based on our conference call discussions.

One signed original and fifteen copies of this letter with the updated compliance review are provided for your use. However, due to the voluminous nature of the attachments associated with the review, only three copies are being provided.

Very truly yours,

E. Douglas Swartz
Nuclear Licensing Administrator

Attachment

cc: J. A. Stevens - LB1
J. G. Keppler - RIII
RIII Inspector - Braidwood

9324N

8412120397 841207
PDR ADDCK 05000456
A PDR

LIMITED DISTRIBUTION
B001
1/2

COMMONWEALTH EDISON COMPANY

BRAIDWOOD STATION

GDC 51 COMPLIANCE REVIEW

TABLE OF CONTENTS

<u>PAGE</u>	<u>SECTION</u>	
1	1	GDC 51 Compliance Review
2	2	Containment Pressure Boundary Limiting Materials
1	2A	Equipment Hatch
2	2B	Piping Penetrations
3	2C	Main Steam Piping Subassembly
4	2D	Main Feedwater Piping Subassembly
6	3	Listing of Attachments
	4	Attachments