FEB 1 4 1985

Alabama Power Company ATTN: Mr. R. P. McDonald Senior Vice President P. O. Box 2641 Birmingham, AL 35291

Gentlemen:

14

SUBJECT: REPORT NOS. 50-348/85-07 AND 50-364/85-07

On January 28-30, 1985, NRC inspected activities authorized by NRC Operating License Nos. NPF-2 and NPF-8 for your Farley facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Should you have any questions concerning this letter, please contact us.

Sincerely,

David M. Verrelli, Chief Reactor Projects Branch 1 Division of Reactor Projects

Enclosure: Inspection Report Nos. 50-348/85-07 and 50-364/85-07

cc w/encl:

W. O. Whitt, Executive Vice President

J. D. Woodard, Plant Manager

W. G. Hairston, III, Manager, Nuclear Engineering and Technical Support

J. W. McGowan, Manager-Safety Audit and Engineering Review

H. O. Thrash, Manager, Nuclear Operations and Administration

W. G. Ware, Supervisor-Safety Audit and Engineering Review

bcc w/encl: (See page 2)

8503080307 850214 PDR ADOCK 05000348 PDR

I IEOI

.4

bcc w/encl: NRC Resident Inspector E. Reeves, Project Manager, NRR Document Control Desk State of Alabama

RII GNeifelt:ht 2/07/85 HWhitener 2/07/85

RII FJape 60 2/13/85

RII ARHERDT 2/13/85