Carolina Power & Light Company

Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429 February 22, 1985

FILE: B09-13510C SERIAL: BSEP/85-0287

Dr. J. Nelson Grace, Administrator U.S. Nuclear Regulatory Commission Region II, Suite 2900 101 Marietta Street N.W. Atlanta, GA 30303

> BRUNSWICK STEAM ELECTRIC PLANT UNIT 1 DOCKET NO. 50-325 LICENSE NO. DPR-71 SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-85-1)

Dear Dr. Grace:

During power operation of Units 1 and 2, appropriate fire barrier LCOs were established on January 21, 1985, for fire door 117 of Unit 1 Battery Room B and fire door 113 of Unit 2 Battery Room B. This was done to permit routing power supply cables through the opened doors to supply space heaters in the rooms. The space heaters were installed to help maintain acceptable room temperatures. On January 28, 1985, the specified seven-day time frames of the subject LCOs were exceeded.

The LCOs and appropriate fire watches will remain in effect until acceptable room temperatures are maintained without reliance upon the space heaters.

Very truly yours,

2:2 C. R. Dietz, General Manager Brunswick Steam Electric Plant

RMP/k1b/LETDR1

Enclosure

cc: NRC Document Control Desk

TE221/0