



Carolina Power & Light Company

85 FEB 19 11:24

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

February 14, 1985

FILE: B09-13510C

SERIAL: BSEP/85-0234

Dr. J. Nelson Grace, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street N.W.
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2

DOCKET NO. 50-324

LICENSE NO. DPR-62

SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-85-1)

Dear Dr. Grace:

During Unit 2 power operation, a Unit 2 fire barrier LCO was established on January 16, 1985, to permit making a four-inch core bore in the Unit 2 Cable Spread Room at fire barrier seal No. CB-1-373. This work was being performed in accordance with an approved plant modification. Due to the amount of time required to complete the involved work and restricted personnel access to the involved work area, and as a result of seasonal extremely cold weather, the specified seven-day time frame of the subject LCO was exceeded by four hours. During the time period the subject LCO was in effect, appropriate stationed fire watches were maintained.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/mcg/LETG2

cc: NRC Document Control Desk

8503120676 850214
PDR ADOCK 05000324
S PDR

OFFICIAL COPY

IE 22 1/0