

Duke Power Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MG01VP)
Huntersville, NC 28078-8985

T. C. McMEEKIN
Vice President
(704)875-4800
(704)875-4809 Fax



DUKE POWER

May 13, 1996

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

Subject: McGuire Nuclear Station
Docket Numbers 50-369 and 50-370
Generic Letter 93-04 "Rod Control System Failure and
Withdrawal of Rod Cluster Assemblies"
Completion of Current Order Timing Modifications and
Trace Surveillances

Gentlemen:

By letter dated February 23, 1995, Duke Power Company committed to implement a current order timing modification and a current order trace surveillance at McGuire Nuclear Station during the end-of-cycle 10 refueling outage for each unit. These modifications and trace surveillances were completed during 1EOC10 and 2EOC10 refueling outages.

If you have any questions concerning this notification, please contact Randy Cross at (704) 875-4179.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'T. C. McMeekin'.

T. C. McMeekin

xc: Mr. S. D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, Georgia 30323

Mr. Victor Nerses
U. S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
One White Flint North, Mail Stop 9H3
Washington, D. C. 20555

Mr. George Maxwell
Senior Resident Inspector
McGuire Nuclear Station

200103

AD30%

9605200445 960513
PDR ADOCK 05000369
P PDR