## Appendix

## NOTICE OF VIOLATION

Illinois Power Company

Docket No. 50-461

As a result of the inspection conducted on February 19 - March 1, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

10 CFR 50, Appendix B, Criterion XV, as implemented by Illinois Power Company Nuclear Power Construction Quality Assurance Manual, Chapter 15, requires noncomforming items be identified and corrected.

Contrary to the above, the NSED disposition in response to BA Field Verification Nonconformance Report No. 65,790 was found to be inadequate in that the disposition states, "Use-as-is, Type B" (written in error), when in fact it was a valid nonconforming condition. This disposition did not identify the cause, resolution, or the corrective action to prevent recurrence of the identified deficiency. For additional details and other examples of this noncompliance, see Paragraph 2.d.(3) of Inspection Report No. 461/85-13(DRS).

This is a Severity Level IV violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

3/20/85 Dated

J. J. Harrison, Chief Engineering Branch