



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA STREET, N.W., SUITE 2900
ATLANTA, GEORGIA 30323-0199

Report No.: 50-395/96-06

Licensee: South Carolina Electric & Gas Company
Columbia, SC 29218

Docket No.: 50-395

License No.: NPF-12

Facility Name: Virgil C. Summer Nuclear Station Unit 1

Inspection Conducted: April 29-May 3, 1996

Inspector: W. W. Stansberry
W. W. Stansberry, Safeguards Inspector

5/31/96
Date Signed

Approved by: P. E. Fredrickson
for P. E. Fredrickson, Chief
Special Inspections Branch
Division of Reactor Safety

5/31/96
Date Signed

SUMMARY

Scope:

This routine announced inspection was conducted in the areas of the Physical Security Program for Power Reactors. The specific areas evaluated were: audits; corrective actions; management support; security program plans; and effectiveness of management control.

Results:

In the areas inspected, no violations were found. Two violations were closed (94-18-01 and 94-18-02). The following strengths and weaknesses to the security program were found:

- Strengths - Minimal back orders of maintenance/repair requests.
 - SEL reportable events were responded to in an effective manner.
 - Effective security maintenance analysis program.
 - Thorough audit program.
- Weakness - Reportable events trend had increased during the last quarter.

Licensee-conducted audits and surveillances were thorough, complete, and effective in terms of uncovering weaknesses in the security system, procedures, and practices. Problems identified were not programmatic; but, indicated an improved awareness of certain procedure requirements was needed. The corrective actions taken were technically adequate and performed in a

9606070215 960531
PDR ADDCK 05000395
PDR
G

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosure(s) this document is decontrolled.

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

2

timely manner. The licensee provided adequate management support to the physical security program. Plan changes reviewed had not decreased the effectiveness of the physical security program. Licensee's effectiveness to control and manage the security program was adequate and appropriate.

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosure(s) this document is decontrolled.

SAFEGUARDS INFORMATION