

ENCLOSURE 2

NOTICE OF DEVIATION

Florida Power and Light Company  
Turkey Point Units 3 & 4

Docket Nos. 50-250 and 50-251  
License Nos. DPR-31 and DPR-41

The following deviation was identified during an inspection conducted on August 13 - September 7, 1984.

Florida Power and Light Company letter L-81-1, dated January 2, 1981, in response to NUREG-0737, states that 40 hours of simulator training will be given to shift technical advisor candidates, unless the individual can demonstrate adequate knowledge in this area.

Contrary to the above, three personnel were utilized as shift technical advisors without demonstrating adequate knowledge or possessing previous operating experience and prior to receiving simulator training.

Please provide in writing, within 30 days of the date of this Notice, a description of corrective actions regarding this deviation, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Date: NOV 01 1984