

RSB

Docket No. 50-361

MAR 19 1985

Southern California Edison Company  
P. O. Box 800  
2244 Walnut Grove Avenue  
Rosemead, California 91770

Attention: Mr. Kenneth B. Baskin, Vice President  
Nuclear Engineering, Safety and Licensing Department

Gentlemen:

Subject: NRC Inspection of Containment Integrated Leak Rate Test  
San Onofre Unit 2

This refers to the inspection conducted by Mr. C. Clark of this office on February 13-23, 1985, of activities authorized by NRC License No. NPF-10, and to the discussion of our findings held with Mr. J. Bognar and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selected examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

No violations with NRC requirements or deviations were identified.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection we will be glad to discuss them with you.

Sincerely,

151

D. F. Kirsch, Acting Director,  
Division of Reactor Safety and Projects

Enclosure:  
Inspection Report No. 50-361/85-05

cc w/enclosure:  
D. J. Fogarty, SCE  
H. B. Ray, SCE  
J. G. Haynes, SCE  
State of CA (Johnson)

bcc: RSB/Document Control Desk (RIDS)  
Resident Inspector  
Mr. J. Martin

RV  
CClark:dh  
3/17/85

TYoung  
3/14/85

FJohnson  
3/14/85

RPate  
3/18/85

DKirsch  
3/18/85

8504110432 850319  
PDR ADOCK 05000361  
PDR

1201