



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX 910-663-2651

February 17, 1984

*Bonney Forge Paul 21*

Mr. R. DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Reference: A) Bonney Letter 3/11/83  
B) Bonney Letter 4/11/83  
C) Bonney Letter 9/16/83  
D) Bonney Letter 1/17/84

Gentlemen,

The following companies have been sent the attached notification form letter along with their required support information in accordance with Reference C.

Submitted,

D. L. Kale  
Quality Control Manager

Enclosures

cc: Dr. W. F. Anderson, M.S.359E/W  
P. R. Benavides  
D. Ketring  
J. A. Leone

8504110548 840217  
PDR PT21 EMVBONF  
84 PDR

IE 19  
1/1  
ORIG TO W.F. Anderson  
Ewfw-359

February 15, 1984

BS&B Safety Systems  
P.O. Box 45590  
Tulsa, OK 74145-0590

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Barr Supply  
Box 451 RR #1  
Channahon, IL 60410

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Mr. L. P. Canuso  
P.O. Box 378  
Deptford, N.J. 08096

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Capitol Pipe  
301 City Line Ave.  
Bala-Cynwyd, PA 19004

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment



February 15, 1984

Chicago Tube & Iron  
2531 W. 48th St.  
Chicago, IL 60632

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Consolidated Pipe  
P.O. Box 2472  
Birmingham, Al 35201

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Dodson Steel  
P.O. Box 279  
Metroatlanta  
Ellenwood, GA 30049

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment



February 15, 1984

Dravo Corp.  
1115 Gilman Ave.  
Marietta, OH 45750

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

EPG Engineered Systems  
P.O. Box B  
Paola, KS 66071

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

EPG Services  
P.O. Box 3031  
Houston, TX 77001

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Gulfalloy  
P.O. Box 52518  
Houston TX 77052

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Guyon Alloys  
950 S. 4th St.  
Harrison, N.J. 07029

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment





**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Hub, Inc.  
2146 Flintstone Dr.  
Tucker, GA 30084

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Hysen Supply  
2425 Hyde Park Blvd.  
Niagara Falls, N.Y. 14305

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in cursive script, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

ITT Grinnell  
P.O. Box 566  
Kernersville, N.C. 27284

Attn: O. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Mr. Robert James  
P.O. Box 1672  
Buffalo, N.Y. 14216

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Guilf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Joliet Valves  
P.O. Box 400  
Minooka, IL

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment





**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Liberty Equipment  
620 East Bruneau  
Kennewick, WA 99336

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in cursive script, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment

February 15, 1984

Marmon-Keystone  
300 Morgan Center Main St.  
Butler, PA 16001

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.


All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,



D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

McJunkin Corp.  
P.O. Box 513  
Charleston, W.VA

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Mutual Manufacturing & Supply  
3300 Spring Grove Ave.  
Cincinnati, OH 45225

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Permutit  
1915 Old Philadelphia Pike  
Lancaster, PA 17604

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment





**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Power Piping  
829 Beaver Ave.  
Pittsburgh, PA 15233

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Pullman Power Products  
P.O. Box 3308  
Williamsport PA. 17701

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Reactor Controls  
1245 S. Winchester Blvd.  
San Jose, CA 95128

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in cursive script, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

B.F. Shaw  
P.O. Box 228  
Wilmington, DE 19899

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Southwest Fab.  
P.O. Box 9449  
Houston, TX 77011

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment





**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Stainless Pipe & Fittings  
37 Rogers St.  
Cambridge, MA 02142

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Taylor Forge Canada LTD  
Hamilton Branch  
P.O. Box 511  
1675 Burlington St. East  
Hamilton, Ontario CANADA L8N3H8

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Tubeco, Inc.  
123 Varick Ave.  
Brooklyn, N.Y. 11237

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Tube-Flo  
301 City Line Ave.  
Bala-Cynwyd, PA 19004

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

A handwritten signature in dark ink, appearing to read 'D. L. Kale'.

D. L. Kale  
Quality Control Manager

Attachment



**Bonney Forge**

Gulf + Western Manufacturing Company

201 West Mount Street, Carlinville, Illinois 62626  
(217) 854-9611, TWX: 910-663-2651

February 15, 1984

Tyler-Dawson  
P.O. Box Drawer X  
Admiral Station  
Tulsa, OK 74112

Attn: Q. A. Manager

Gentlemen:

During an internal review of quality assurance records it has come to our attention that some material was delivered to you with incomplete documentation.

The purpose of this letter is to advise you of certain materials shipped from the Carlinville plant lacking the chemical overcheck requirement of Para. NCA-3867.4(e)(2).

It should be noted that we are talking about the chemical overcheck only; not any essential production steps used in the manufacture or steps to assure traceability.

All of the subject material is heat traceable through our own plant, the material suppliers' warehouse and back to the mill of manufacture. In addition, all suppliers' warehouses and manufacturing mills appear on our audited and approved vendors lists throughout the period in question.

The attached list of purchase order numbers, item numbers, heat numbers and fitting descriptions is a complete list of the affected items based on an in-depth review of our files back to January 1977.

Please contact my office for any and all additional information you require to bring about a prompt and proper resolution of this matter.

Mr. P. R. Benavides, Quality Assurance Manager, Bonney Forge Division, Allentown, PA (215) 435-9611, is also available should you wish to discuss the matter with him.

Submitted,

D. L. Kale  
Quality Control Manager

Attachment