

MAR 12 1982

43

Mr. Leonard L. Webb  
GSA Buildings Manager (WPFNH)  
Hyattsville Field Office  
6525 Belcrest Road, Suite 1010  
Hyattsville, MD 20782

Dear Mr. Webb:

Subject: Exit Marking - Willste Building

The enclosed memorandum documents unsatisfactory conditions in the subject building.

Please advise as to the time frame for resolving these deficiencies.

Sincerely,

Original Signed By  
Richard E. Iselin

Richard E. Iselin, Chief  
Building and Operations Branch  
Division of Facilities and  
Operations Support

Enclosure: As stated  
cc: SOakley (WPRUC)

DISTRIBUTION:

RF (BOB)

Subj. File, BOB

REDuck, BOB

JB Frye, S&H

8501240131 840516  
PDR FOIA  
LEVY84-254 PDR

OFFICE	BOB/FOS/ADM	BOB/FOS/ADM				
SURNAME	REDuck:mhp	REIselin				
DATE	3/12/82	3/12/82				