

## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

PDR-016 LPDR

Docket No. 50-460

JUL 2 3 1984

Ms. Nina Bell Nuclear Safety Analyst Nuclear Information and Resource Service 1346 Connecticut Avenue, NW 4th Floor Washington, DC 20036

IN RESPONSE REFER TO FOIA-84-160

Dear Ms. Bell:

This is a final response to your letter dated March 8, 1984, in which you requested, pursuant to the Freedom of Information Act (FOIA), copies of documents regarding the Construction Appraisal Team inspection conducted in 1983 of WPPSS Nuclear Project No. 2, with the exception of the final CAT Report and documents already made available pursuant to your previous FOIA requests 83-524, 83-538, and 83-641.

As you agreed during a telephone conversation with Mrs. Pappas on July 17, 1984, we are enclosing a list of documents maintained by Region V which are subject to your request. You will submit another FOIA request for any of the listed documents in which you may be interested.

Sincerely

This completes action on your request.

7. M. Felton, Director

Division of Rules and Records

Office of Administration

Enclosure: As stated

## LISTING OF DOCUMENTS RELATING TO FOLA-84-160 - REQUEST FROM NINA BELL FOR DOCUMENTS REGARDING THE CAT INSPECTION CONDUCTED IN 1983 AT WPPSS-2

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
1	1/25/79	1	Letter-M.E. Cunningham Co./Big Four Welding Equipment Co. RE: Stamp Requirements
2	4/17/79	1	Letter-M.E. Cunningham Co./Wm. H. Krueger Co. RE: Stamp Requirement
3.	7/20/79	5	Letter-Burns & Roe. J. Byrnes/K. Cowan Rigid Conduit Connections Electrical Equipment
4	11/8/79	1	Letter-M.E. Cunningham Co./LMT., IMT., -RE: Stamp Marks on Welds
5	11/26/80	8	Memo-Burns & Roe, J. Braveman/R. Snaith Seismic Qualifications of Seismic Category I swithgear/MCC/Control cabinets with top entrigid conduit
6	5/26/81	6	Memo-NRC/B. Faulkenberry/A. Toth-Work statement for WNP-2- Independent Measurements
7	6/22/81	4	Memo-NRC/A.Toth/B.Faulkenberry-Work statement for WNP-2 Independ Measurements
8	6/26/81	1	Memo-WPPSS D Welch/J. Johnson, Bechtel Radiograph Review Correct action. Enclosure 5/23/79 LMT Report of Visual and Ultrasonic Examination 16 pages
9	7/8/81	3	Meeting Notes: WPPSS-Bechtel Status of RT Review of WBS Pipe Wel
10	7/9/81	1	Memo-WPPSS-R. Johnson/J. Harrington-NRC Independent Measures Van Utilities
11	7/22/81	1	Letter-Bechtel-M. Jacobson/R. Johnson Bechtel-MCAR No. 1 Enclosure-7/21/81 Management Corrective Action Request 1-2 pages
12	8/4/81 -	1	etter-Bechtel-T. Mangelsdorf/W.Bibb-Bechtel MCAR No. 1 Enclosure - Weld Cutout Details - 1 page
13	8/24/81	1	etter-WPPSS-W. Bibb/T. Mangelsdorg- Corrective Action Plan WBS

Radiographs

ì

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
14	9/29/81	2	Memo-J. Crews/E. Jordan-Possible problem at WNP-2 regarding quality of Radiographs and integrity of safety related welds
15	11/11/81	1	WPPSS telephone record-R.Johnson/J. Elin-RE: Licensee reports to NRC under 10CJR50.55 (a) regarding radiographs
16	12/21/81	1	WPPSS-R.Matlock/R. Engelken-RE: Licensee reports to NRC under 10CFR50.55 (a) regarding Radiographs
17	12/22/81	3	Status Report (G.Stohll) Bechtel-Reverification of WBB Radiograph Enclosure-12/16/81-Reverification of Radiographs - 1 page
18	2/2/82	2	Status Report (G. Stohill) Bechtel-Reverification of WBG Radiogram Enclosure-1/27/82-Reverification of Radiographs -1 page
19	3/11/82	1	WPPSS-R. Matlock/R. Engelken-Licensee report to NRC under 10CRF50.  (a) regarding radiographs Enclosure-Interia Report #2-2 pages
20	4/8/82	4	Amendent 1, work instruction reverification of WBS Radiographs Attachment-page 1- of initial work instruction - 1 page
21	4/12/82	1	UPPSS-R. Matlock/R. Engelken-Licensee report to NRC under 10CFR50.  (a) regarding radiographs
22	4/22/82	1	Letter-Bechtel-T. Mangelsdorf/R. Johnson-Reverification WBG Pipe Weld Radiographs
23	5/18/82	1	WPPS-R. Matlock/R. Engelken-Licensee reports to NRC under 10CFR50.  (a) regarding radiographs
24	7/28/82	2	Memo-NRC-J. Durr/R. Dodds-Region V Utilization of the Mobile NDF.
25	8/3/82 •	1	Memo-WPPSS-R. Johnson/Distribution-Nuclear Regulatory Commission NDE Van

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
26	8/6/82	1	Memo-Bechtel-D. Johnson/S. Hierzer-Supply System IOM QA2-82-91. dated 8/3/82, same subject.
27	8/16/82	1	Memo-NRC-A.Toth/R. Dodds-NDE Van Schedule
28	9/1/82	1	WPPSS-R. Matlock/R. Engelken-Licensee reports to NRC Under 10CFR50 (a) regarding radiographs Enclosure-Final Report-3 pages
29	9/1/82	7	Final Report (draft), Bechtel Reverification of WBG/Bovee Crail Radiographs
30	9/16/82	1	Memo-WPPSS-J.Harrington/S.Hansen-NRC Testing Trailer
31	10/14/82	2	Letter-WPPSS-H. Crisp/T. Mangelsdorf-Nuclear Project No.2-Contract C-500-Actions resulting from NRC NDE Van Visit
32	10/22/82	3	Letter-Bechtel-T. Mangelsdorf/H. Crisp-Supply System Nuclear Projection. 2-Contract C-500-Action plans to resolve questions raisded by NRQ NDE Van visit.
33	11/3/82	5	Memo-NRC-A. Toth/H. Kerch-Casting of Weld Roof of 4'line MSLS-084-7.10FW3R1.
34	11/24/82	1	NRC Inspection open item (Form) 82-19-02
35 .	11/29/82	1	NRC Findings open item (Form) 82-19-01
36	12/30/82	1	WPPSS-G. Bouchey/A. Schwencee (NRC) Safety Evaluation Report (RUREG-0892) Confirmatory Issue No. 7-Component Supports Enclosure-Component Support Assessment-11 pages
37	1/17/83	1	Letter-WPPSS-G. Bouchey/A. Schwencer (NRC) Visual examination acceptance criteria for reverification inspection of Welded Structures (QVI-09, Rev 0) 1 page Attachment-Visual examination acceptance criteria-9 pages

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
38	1/19/83	1	Memo-Bechtel-W.Koepka/R. Johnson-Resolution of Items NRC Report No. 50-397/82-19 Enclosure-12/21/82-same title-15 pages
			Literague 12/21/02 Same Citte-15 pages
39	1/20/83	3	Letter-WPPSS-G. Bouchey/A. Schwencer (NRC) WNP-2 Plant Verification Program third TAA Audit (cover letter plus page 3 and 18 of attachment)
40	1/14/83	2	NRC Findings/concern cover sheet
41	2/23/83	1	Startup Problem Report-109.25 C0500-1526 Conduit Installation
42	3/8/83	2	Letter-WPPSS-J. Honekamp/R. Laney (TAA) Response to TAA Audit report dated 1/10/83 (cover letter and page four of attachement)
43	3/23/83	1	Letter-WPPSS to NRR Schwencer (¿VI-09, Revision 1) Enclosure-Procedure QVI-09 Rev. 1-Special Structural Steel reinspection criteria-12 pages
44	4/8/83	1	Letter-Bechtel-J. Gatewood/R. Johnson Reverification program for WBG/Bovee Crail Radiographs
45	4/8/83	1	Memo-NRC-A.Toth/H. Kirch-Ref: 50-397/82-19
46	4/21/83	1	NRC-Finding/concern cover sheet 82-19-01/02
47	4/21/83	1	Bechtel-Memo-C.Headrick/J. Gatewood-RE: NRC Report 50-397/82-19 Enclosure-Radiograph reader sheets: August 26, 1976 EDR-890-3 January 19, 1977 EDR-876-7 September 30, 1976 FDR-954-5
48	5/13/83	1	Memo-Bechtel-G.Finnan/D. Johnson-ASME-Section III, Class I-RT File Phase II Reverification Program Enclosure-list of welds- 5 pages
49	6/9/83	2	Memo-F. Pimentel/S. Stahl-Radiographic Film-Review concerns as 6/9/83

NO.	DATE	NO. PAGES	DECONTEMION
or restrict to the same of			DESCRIPTION
50	6/10/83	8	Chronology of Significant Events relating to Radiographic Reverification
51	6/21/83	1	Letter-Burns & Roe A. Cygleman/W. Marini (NRC) conduit connection to Class IE Electrical Component and Equipment Attachment-April 23, 1982-Specification Page 16A-17 1 page
52	6/22/83	3	Radiograph CAT concerns followup sheets
53	7/1/83	2	Memo-NRC-J. Taylor/R. Vollmer-WNP-2-Component Support Design and Construction
54	7/1/83	8	Letter-WPPSS-C. Carlise/D. Sternberg (NRC) Report 83-14 Rebar
55	7/1/83	2.	Memo-Vollmer, Director from Taylor WNP-2, Component Support Design and Construction (QV1-09)
56	7/1/83	2	Memo-(NRC) Richard Vollmer, Director-from James M. Taylor, Direct Subject-WNP-2, Component Support Design and Construction
57	7/15/83	2	Letter-WPPSS-C.S. Carlisle-/J. B. Martin (NRC) Subject-Nuclear Project 2-Construction Assessment Team issues Enclosure-87 pages-photos 49 pages
58	7/15/83	2	Letter-WPPSS C. Carl'sle/J. Martin (NRC) Construction Assessment Issues (w/o attachments)
59	7/26/83	1	50-397/83-29 letter to WPPSS-NRC inspection reports specifically referring to CAT identified issues.
60	7/27/83	24 48 photos	Check of excavation fuel pool wall, with drawings, pictures, Negative number 1-50 location sheet Job 83-869
61	7/28/83	1	Letter NRC-D. Sternberg/C.Carlisel (WPPSS) Construction Assessment team in May, June 1983.

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
62	7/28/83	1	Letter-WPPSS-C. Carlise/J. Martin (NRC) Ref. 83-38-01, 10CFR50.55 (e) #269 Weld repairs
			Enclosure-interim report bechtel repair of wrong weld area-2page
63	7/28/83	4	10CFR50.55(e) repair of wrong weld area
64	7/29/83	8	Letter-WPPSS-C.Carlise/D.Sternberg (NRC) Amended response 83-14-03
65	8/1/83	1	Letter-WPPSS-C. Carlisle/D. Sterhberg (NRC)Inspection report 83
66	8/2/83	1	Memo-NRC-R. Heishman/G.Bagchi-Rigid conduit connections to electrical equipment -Enclosures at WNP-2
67	8/5/83	1.	Letter-WPPSS-C. Carlisle/D. Sternberg-inspection report 83-22 Notice of Deviation
			Enclosure-reply to notice of deviation-2 pages
68	8/11/83	2	WPPSS-C. Carlise/J. Martin (NRC) 50.55 (e) #270 Bolts and Fasteners (83-38-01)
69	8/12/83	4	Memo-Taylor from Vollmer-Responce to 7/1/83 Memo-WNP-2 Component Support Design and Construction
70	8/12/83	1	Memo-James M. Taylor (NRC) Richard H. Vollmer-WNP2-Component support Design and Construction
			Enclosure-Memo: A. Schwencer, Chief (NRC) Robert J. Bosnak, Chief WNP-2-Component Support Design and Construction -Attachment-WNP-2-Docket No. 50-397
71	8/15/83	3	Letter WPPSS-C.Carlisle/J. Martin (NRC) Construction Appraisal Team Issues
			Attachments-Description of Seven Programs to address broad issues raised by the CAT-51 pages
72	8/16/83	1	letter to WPPSS-NRC Inspection reports specifically referring to CAT identified issues-50-397/83-36
			500 BB (1987년 1987년

TEM NO.	DATE	NO. PAGES	DESCRIPTION
73	8/18/83	2	Memo-Ray Auluck, Licensing Br.#2, R.T. Dodds (NRC) Reactor Licensing Assistance in Closing RV Construction deficiency issue regarding WNP-2 (WPPSS) Docket #50-397
74	8/30/83	1	Letter-NRC-A.Schwencer/D.Mazur (WPPSS) Rigid Conduit Connection to electrical equipment-enclosures
75	8/30/83	1	Letter-WPPSS-50-397/83-38-NRC Inspection Report Specifically Referring to CAT identified issues.
76	9/8/83	33	Bechtel, D.Johnson/H.Crisp-Resolution of NRC CAT Concerns regarding Non destructive Examination
77	9/9/83	6.	WNP-2-Project Position Paper No.26-Adequacy of Quality Class II/ Seismic Category I-Piping Support prepared by-D.C. Timmins Attachment I-Letter-C.S. Carlise/J.B.Martin (NRC) Nuclear Project 2-Construction Assessment Team Issues-Report and Letter-24 pages
78	9/9/83	37	QVP/CAT Analysis Master Log
79	9/15/83	1	WPPSS-C.Carlisle/J. Martin-Licensee Reports to NRC under 10CFR50.  (a) regarding radiographs Enclosure-Final Report-3 pages
80	9/15/83	1	Memo: NRC R.Dodds/A.Toth-Unresolved Item 397/83-38-02 RE: Gilbert Commonwealth
81	9/16/83	2	WPPSS-G.C.Sorensen/A. Schwencer-Nuclear Project #2, Clarification of the use of Project Instruction QV1-09 Attachment-WNP-2-Amendent No. 30-6/83-1 page
82	9/16/83	66	Letter (with attachements) WPPSS to Region V-Martin-Concrete Reba (83-38-10)
83	9/16/83	2	Letter-WPPSS-G. Sorensen/A. Schwencer (NRC) Clarifications on the use of Project Instruction QV1-09 Attachement-Draft FSAR page 3.8-190 1 page

ITEM	DATE	NO. PAGES	DESCRIPTION
NO.	9/19/83	-	
04	9/19/03	1	602-83.847-WPPSS letter to NRC in reply to inspection report 50-397/83-38
	* ::' "		Attachment 1-responce to inspection report 83-38-2 pages Attachment 2-responce to inspection report 83-38-5 pages
85	9/21/83	8	WPPSS Quality Verification program overview report-Section 8.0 QVP/CAT comparison
86	9/21/83	2	Memo-NRC-T.Bishop/E. Jordan atalPotentially general issue data sheet concerning repairing wrong welds
87	9/22/83	4	letter-Gilber-Commonwealth to Burns & Roe-unresolved item-397/83-38
88	. 9/22/83	2	letter-Gilbert-Commonwealth to Burns & Roe-RE: WPPSS-WNP-2-contract C-0208-NRC, Office of Inspection Enforcement Report-No.50-397/83-38 8/29/80 Attachement to CCBR-F-83- pages 4 and 5
89	9/26/83	4	GO2-83-870-WPPSS letter to NRC in reply to inspection report 50-397/83-38
			Enclosure-Project position paper No.26-Adequacy of Quality Class   Seismic Category I Piping Supports - 30 pages
			Enclosure-Sept.22,1983-Stone & Webster Report Engineering Inspection and Evaluation of Quality Class II/Seismic Category I Pipe Support 34 pages
90	9/28/83	1	Letter NRC/T.Bishop/C.Carlisle(WPPSS) in reply to inspection report 50-397/83-38.
91	9/28/83	1	Letter (WPPSS) C.J.Carlisle/Biship-cover letter-letter 9/19/83 WPPSS C.S. Carlisle/J.B. Martin (NRC) RE-inspection report 83-38- Notice of Violation
			Attachment No. 1-WPPSS-Nuclear Project No. 2-Cocket No. 50-397
			License No. CPPR-93-Response to inspection report 83-38-Notice of violation-2 pages
			Attachement No.2- same as attachment No.1- 5 pages
			Booklet File Copy-Responce to Inspection Report 83-38-Notice of Violation

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
91 (con't)			"Section E"-Evaluation of Concrete and Reinforcing Steel-63 pages Folder Containg-WNP-2-Concrete Excavation Reactor Building Photographs- 65 prints
92	9/29/83	1	GO2-83-874-WPPSS to NRC in reply to inspection report 50-397/83-38 Attachment 1-response to inspection report 83-38 Notice of Violation-3 pages
93	10/4/83	1	NRC-T.W. Bishop/C.S.Carlisle (WPPSS) Violation "B" Nuclear Project 2-Report 83-38. letter-9/26/84-C.Carlisle (WPPSS) J.B. Martin (NRC) Report 83-38 Violation "B" Attachment 1-4pages-Report/letters-64pages
94	10/6/84	1	Memo-(NRC) R. Auluck/A. Schwncer-Forthcoming Meeting with WPPSS-for discussion of CAT findings in the Civil and Structural Construction area.  Attachments and drawings- 69 pages
95	10/7/83	1	Letter-T.W.Bishop (NRC) C.S.Carlisle-WNP-2-Correction Item "F" Attachment-letter-9/29/83-C.S. Carlisle/J.B. Martin-Report 83-38 "F"-1 page Attachment 1-3 pages
96	10/7/83	1	Letter-NRC-T.Bishop-C. Carlisle (WPPSS) RE: Inspection Report- 50-397/83-38
'17	10/11/83	2	Quality Assurance Surveillance Report 83-292-SS. Enclosure-9/15/83-Startup Deficiency Report SDR-M-12890-1 page Enclosure-7/1/83-Nonconformance Report 2175-2 pages Enclosure-8/26/83-BESTCO NDE- Report N-406-3 pages Enclosure-8/13/83-BESTCO NDE- Report N-309-1 page Enclosure-8/1/83-BESTCO Radiographic Examination Report-1 page
98	10/19/83	1	Task Interface Agreement #14135-Construction Deficiencies

with NRC 10/14/83 in Bethesda, Maryland Attachment 1-NRC Inspection Item 83-38/02-Quality Class I As-B Program- 165 pages Attachment 2- SWEC Third-Party Review of QC1 and QC11/SCI pipe Supports- 89 pages  100 10/26/83 1 G02-83-973-WPPSS letter to NRC-RE: Inspection Report 50-397/83 Enclosure-10/18/83 Letter- Stone & Webster-R. Westfahl/H.Crisp (WPPSS) QCI and QCII/SCI Pipe Supports, WPPSS Meeting with the and Stone & Webster Engineering Corporation 1 page-101 pages o calculations Enclosure-9/15/83 Report: Engineering Inspection and Evaluatio QCI Pipe Supports and Small Bore Piping- 56 pages  101 10/31/83 1 G02-83-996-letter to NRC-RE: Inspection Report 50-397/83-38 Attachment-Addendum to Response to Inspection Report 83-38 Evaluation of Concrete and Reinforcing Steel- 8 pages  102 10/31/83 9 Letter-WPPSS to Region V-Martin with attachment 1- Evaluation of Concrete and Reinforcing Steel  103 11/1/83 1 Letter-WPPQS-S. Sorensen/A. Schwencer-Use of Rigid Conduit Connections to Electrical Equipment- Enclosures  104 11/2/83 1 Letter-50-397/83-49-NRC Inspection Reports Specifically Referr to CAT Identified Issues.  105 11/10/83 1 NRC-T. Bishop/C. Carlisle (WPPSS) NRC Acknowledgement letter RE: Inspection Report 50-397/83-38  106 11/10/83 2 Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlis RE: Inspection Report 50-397/83-38	ITEM NO.	DATE	NO. PAGES	DESCRIPTION
Enclosure-10/18/83 Letter- Stone & Webster-R. Westfahl/R.Crisp (WPPSS) QCI and QCII/SCI Pipe Supports, WPPSS Meeting with the and Stone & Webster Engineering Corporation 1 page-101 pages of calculations Enclosure-9/15/83 Report: Engineering Inspection and Evaluation QCI Pipe Supports and Small Bore Piping- 56 pages  101 10/31/83 1 G02-83-996-letter to NRC-RE: Inspection Report 50-397/83-38 Attachment-Addendum to Response to Inspection Report 83-38 Evaluation of Concrete and Reinforcing Steel- 8 pages  102 10/31/83 9 Letter-WPPSS to Region V-Martin with attachment 1- Evaluation of Concrete and Reinforcing Steel  103 11/1/83 1 Letter-WPPQS-S.Sorensen/A. Schwencer-Use of Rigid Conduit Connections to Electrical Equipment- Enclosures  104 11/2/83 1 Letter-50-397/83-49-NRC Inspection Reports Specifically Referr to CAT Identified Issues.  105 11/10/83 1 NRC-T. Bishop/C. Carlisle (WPPSS) NRC Acknowledgement letter RE: Inspection Report 50-397/83-38  106 11/10/83 2 Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlis RE: Inspection Report 50-397/83-38	99		1	Inspection Report 50-397/83-38 Notice of Violation-RE: Meeting with NRC 10/14/83 in Bethesda, Maryland Attachment 1-NRC Inspection Item 83-38/02-Quality Class I As-Built Program- 165 pages Attachment 2- SWEC Third-Party Review of QC1 and QC11/SCI pipe
Attachment-Addendum to Response to Inspection Report 83-38 Evaluation of Concrete and Reinforcing Steel- 8 pages  102 10/31/83 9 Letter-WPPSS to Region V-Martin with attachment 1- Evaluation Concrete and Reinforcing Steel  103 11/1/83 1 Letter-WPPQS-S. Sorensen/A. Schwencer-Use of Rigid Conduit Connections to Electrical Equipment- Enclosures  104 11/2/83 1 Letter-50-397/83-49-NRC Inspection Reports Specifically Referr to CAT Identified Issues.  105 11/10/83 1 NRC-T. Bishop/C. Carlisle (WPPSS) NRC Acknowledgement letter RE: Inspection Report 50-397/83-38  106 11/10/83 2 Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlis RE: Inspection Report 50-397/83-38	100	10/26/83	1	Enclosure-9/15/83 Report: Engineering Inspection and Evaluation
Concrete and Reinforcing Steel  103 11/1/83 1 Letter-WPPQS-S. Sorensen/A. Schwencer-Use of Rigid Conduit Connections to Electrical Equipment- Enclosures  104 11/2/83 1 Letter-50-397/83-49-NRC Inspection Reports Specifically Referr to CAT Identified Issues.  105 11/10/83 1 NRC-T. Bishop/C. Carlisle (WPPSS) NRC Acknowledgement letter RE: Inspection Report 50-397/83-38  106 11/10/83 2 Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlis RE: Inspection Report 50-397/83-38	101	10/31/83	1	Attachment-Addendum to Response to Inspection Report 83-38
Connections to Electrical Equipment- Enclosures  104 11/2/83 1 Letter-50-397/83-49-NRC Inspection Reports Specifically Referr to CAT Identified Issues.  105 11/10/83 1 NRC-T. Bishop/C. Carlisle (WPPSS) NRC Acknowledgement letter RE: Inspection Report 50-397/83-38  106 11/10/83 2 Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlisle RE: Inspection Report 50-397/83-38	102	10/31/83	9	Letter-WPPSS to Region V-Martin with attachment 1- Evaluation of Concrete and Reinforcing Steel
to CAT Identified Issues.  105	103	11/1/83	1	
RE: Inspection Report 50-397/83-38  Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlis RE: Inspection Report 50-397/83-38	104	11/2/83	1	Letter-50-397/83-49-NRC Inspection Reports Specifically Referring to CAT Identified Issues.
RE: Inspection Report 50-397/83-38	105	11/10/83	1	
이 경기가 되는 것이 되었다. 이 경기를 받는 것은 사람들이 가지 않는 것이 되었다. 나는 가지 않는 것이 되었다.	106			Letter-T.W. Bishop/C.S. Carlisle-letter-J.B.Martin/C. S. Carlisle RE: Inspection Report 50-397/83-38 Attachment-Addendum to Responce to Inspection Report 83-38 -5 pages

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
107	11/15/83	1	Letter-G.C. Sorensen (WPPSS) J.B. Martin (NRC) Project No. 2- Inspection Report 50-397/83-38. RE: Letter, GO2-83-973-dated 10/ Attachment-Engineering Inspection and Evaluation of Quality Classic Category I Pipe Supports-WNP#2-prepared for WPPSS-9/22/83/Stone & Webster Eng. Corp 33 pages
108	11/15/83	1	WPPSS-G.Sorensen/A.Schwencer (NRC) Inspection Report 83-38-Notice of Violation-Concrete Attachment-1-Addendum to Responce to Inspection Report 83-38-Notice of Violation Evaluation of Concrete and Reinforcing Steel 11 pages Attachment 2- Summary of Structural Member Involved- 3 pages Attachment 3- Excerpt from Paper 3047 of American Society of Engineers -10 pages Attachment 3- Burns and Roe Calculations 6.19-137, Oct. 18, 84. 7 pages Attachment 4- Burns and Roe Calculations 6.19-137, Oct. 19,81. 8 pages
109	11/22/83	1	WPPSS-G. Sorensen/J. Martin (NRC) NRC Inspection Report 83-38 Notice of Violation
110	11/22/83	1	GO2-83-1084-Letters-NRC in reply to Inspection reports 50-397/90 acknowledgement Enclosure-Westinghouse Raceway Walkdown and Evaluation Summary-14 pages
111	11/30/83	2	Memo: Thomas M. Novak, Assistant Director for Licensing, DL from-James P Knight (NRC) WNP 2-Component Support Design and Construction.  Attachment- MEB Input to CAT Findings Evaluation- 5 pages
112	11/30/83	1	Letter 50-397/83-47-NRC Inspection Reports Specifically referring CAT Identified Issues.
113	12/06/83	1	Letter-T.W.Bishop (NRC) G.C. Sorensen (WPPSS) Responce to Item 83-38 Notice of Violation File Copy-Letter-11/22/83-G.C. Sorensen (WPPSS) J.B Martin (NRC)

ITEM NO.	DATE	NO. PAGES	DESCRIPTION
113 (con't)			cover letter for Report "Westinghouse Raceway Walkdown and Evaluation Summary-13 pages
114	12/06/83	1	(NRC) T.Bishop/C. Carlise (WPPSS) Letter-Inspection Report 50-397/83-38
115	12/16/83	2	GO2-83-1167-RE: Inspection Report 83-38, Notice of Violation-Con- Enclosure-Sketches of Concrete Beams-2B5, 2B11, and 2B25-3 pages
116	12/20/83	1	Letter-James P. Knight (NRC) Thomas M. Novak, Div. of Licensing RE: WPPSS Nuclear Project #2, Docket 50-397 Enclosure-Safety Evaluation Report Supplement Resolution of Constuction Discrepancies in Concrete Structures- Structural and Engineering Branch 7-pages
117	1/05/84	1	50-397/83-56-Letter to WPPSS-NRC Inspection Reports Specifically Referring to CAT Identified Issues
118	1/06/84	1	50-397-83-56-Letter to WPPSS-NRC Inspection Reports Specifically Referring to CAT Identified Issues
119	2/10/84	1	Memo: R.T. Dodds (NRC) R. Auluck (NRR) RE: WNP-2 SSER-4 Section ! CAT Inspection
120	3/16/84	1	Folder-FOIA 84-160-Nina Bell Fo DOC. RE: CAT Inspection Conducted in 1983 at WPPSS-2-14 pages FAX: copy also (same material - 14 pages)
121	3/20/84	1	50-397/84-01-Letter to WPPSS-NRC Inspection Reports Specifically Referring to CAT Identified Issues.
122	8/4/84	16	Bechtel Project Response Schedules to NRC CAT Findings and QVP Schedules
123	8/11/84	1	Memo (NRC) A.Toth/G. Bagchi- Rigid Conduit Connections to Electric Equipment Enclosures at Washington Nuclear Plant #2

ITEM NO.	DATE	NO. PAGES		DESCRIPTION	
	No date	Folder	Reactor Building Con	ncrete Photographs- 2 p	pages and 64 photos
	No date	2	Question/response Regarding RPV 3" Anchor Bolts Attachment 1-Jan 8, 1973 Specification -page SH-9- 1 page Attachment 2-Sept. 30, 1974 Letter PYBUS D. Barnes/S. Dahm (BOVEE-CRAIL) Certificate of Compliance- 2 pages Attachment 3- Sept 18, 1974 Memo: Burns & Roe-R.White/L. Verderber Response to Audit WNP-2-36 - 1 page Attachment 4- Oct. 18,1974 Memo: Burns & Roe-J. Verderber/R.White Section 5H Quality Assurance Requirements- 1 page Attachment 4(a)- Dec. 31, 1974-Memo: H. Flexer/R. White- Certifican of Compliance 1-page Attachment 5- July 11, 1983- WPPSS Memo: T. Stanley/W. Willier Class I Supports, 71 Edition, W.71 Addenda 1-page Attachment 6- Specification page 5-H-9 Rev. 2- 1 page Attachment 7- Feb. 26, 1981- Request for Information CS-CM-1821 Documentation Requirements Structural Steel 1-page Attachment 8- Anchor bolt drawing T129E- 2 pages Attachment 9- Excerpt from ASTM A193-73 8 pages		
	No date		Bechtel, and the NRG CAT efforts which is Independent NDE Van Radiographic interpolations Radiographic interpolations Radiographic Film In Radiographic Interpolation	efforts retation Weld Quality Fretation Weld Quality Fretation Weld Quality Fretation Sheets- 171 pages retation Sheet-1 page	Rejects- 64 pages
	No date	5	Program description NRC inspection repo 50-397/81-15 50-397/82-01 50-397/82-14 50-397/82-18	for resolving NDE con- rts relating to the Rai 50-397/82-19 50-397/82-24 50-397/83-03 50-397/83-22	cerns-5 pages diography issue 50-397/83-29 50-397/83-35 50-397/83-38

\*

ITEM NO.	DATE	NO. PAGES	DESCRIPTION by Bob Dodde
NO.	No date		Construction appraisal team CAT inspection-written by Bob Dodds copy to R. Auluck, NRR - 11 pages
	No date	2	Issue raised by CAT- Respones provided by WPPSS "3" embedded anchor bolts Attachment #1- Documentation-1 page Attachment #2- Pybus Steel Co2 pages Attachment #3- Burns & Roe-1 page Attachment #4- Burns & Roe-2 pages Attachment #5- Memo-WPPSS Attachment #6- Documentation Attachment #7- Documentation Attachment #8- Documentation Attachment #9- Standard Specifications for Alloy-Steel and Stainle Bolting Materials for High-Temperature Services- 8 pages
	No date	3	List and copies of Radiograph Reverification Program NCR's 40 pages of copies of listed noncoformance reports



## Nuclear Information and Resource Service

1346 Connecticut Avenue NW. 4th Floor, Washington, D.C. 20036 (202) 296-7552

March 8,1984

Director
Office of Adminstration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

FOIA -84-160

Qu'd 3-9-84

## FREEDOM OF INFORMATION ACT REQUEST

To whom it may concern:

Pursuant to the Freedom of Information Act, 5 U.S.C. 522, as amended, the Nuclear Information and Resource Service requests the following documents regarding Washington Public Power Supply System Nuclear Project No. 2. Please consider "documents" to include reports, studies, test results, correspondence, memoranda, meeting notes, meeting minutes, working papers, graphs, charts, diagrams, notes and summaries of conversations and interviews, computer records, and any other forms of written communication, including internal NRC Staff memoranda.

Pursuant to this request, please provide all documents prepared or utilized by, in the possession of, or routed through the NRC related to:

1. The Construction Appraisal Team inspection conducted in 1983 of WPPSS Nuclear Project No. 2, with the exception of the final CAT Report, and documents already made available pursuant to FOIA requests 83-524 (BELL), 83-538 (BELL) and 83-641 (BELL).

In our opinion, it is appropriate in this case for you to waive copying and search charges, pursuant to 5 U.S.C. 552(a)(4)(A) "because furnishing the information can be considered as primarily benefiting the general public." The Nuclear Information and Resource Service is a non-profit organization serving local organizations concerned about nuclear power and providing information to the general public.

Sincerely,

Nina Bell Nuclear Safety Analyst 8405250360