

NOTICE OF VIOLATION

Duke Power Company
McGuire Nuclear Plant

Docket Nos. 50-369 and 50-370
License Nos. NPF-9 and NPF-17.

During an NRC inspection conducted on April 26 through June 15, 1996, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

Technical Specification 6.8.1 requires that written procedures be established, implemented, and maintained covering the activities in the applicable procedures recommended in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Contrary to the above, on April 28, 1996, the licensee failed to adequately implement the requirements of Procedure OP/2/A/6100/SU-1, Mode 6 and Core Alterations Checklist. This procedure requires all Performance Tests required for Mode 6 to be within their surveillance interval. This procedure was completed for Mode 6 entry; however, Performance Test PT/2/A/4350/03A, Electrical Power Source Alignment Verification had not been performed as required.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Duke Power Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, U.S. Nuclear Regulatory Commission, Region II and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice.

Dated at Atlanta, Georgia
this 3rd day of July, 1996

Enclosure 1