

Maine Yankee

RELIABLE ELECTRICITY SINCE 1972

EDISON DRIVE • AUGUSTA, MAINE 04330 • (207) 622-4868

October 13, 1992

MN-92-103

JRH-92-124

UNITED STATES NUCLEAR REGULATORY COMMISSION
Attention: Document Control Desk
Washington, DC 20555

References: (a) License No. DPR-36 (Docket No. 50-309)
(b) MYAPCo Letter to USNRC dated September 23, 1991 (MN-91-134)
(c) USNRC Letter to MYAPCo dated October 29, 1991; Inspection Report No. 50-309/91-17


Subject: Inspection Report 91-17

Gentlemen:

In our correspondence to you, Reference (b), Maine Yankee stated that we planned to complete the vortexing calculations and the mid-loop procedure by September 1, 1992. The loop accuracy calculations for residual heat removal (RHR) flow and reactor coolant system (RCS) temperature indications needed to support the mid-loop procedure steps have been delayed.

Maine Yankee now expects to complete the mid-loop procedure by March 1, 1993. Please contact us should you have any questions regarding this matter.

Very truly yours,



James R. Hebert, Acting Manager
Licensing & Engineering Support Department

JVW/jag

c: Mr. Thomas T. Martin
Mr. Charles S. Marschall
Mr. E. H. Trottier
Mr. Patrick J. Dostie

200056

9210210135 921013
PDR ADDCK 05000309
Q PDR

JE01 1/0