

Maine Yankee

RELIABLE ELECTRICITY SINCE 1972

EDISON DRIVE • AUGUSTA, MAINE 04330 • (207) 622-4868

November 4, 1992

MN-92-117

JRH-92-150

UNITED STATES NUCLEAR REGULATORY COMMISSION

Attention: Document Control Desk

Washington, DC 20555

References: (a) License No. DPR-36 (Docket No. 50-309)
(b) USNRC Letter to MYAPCo dated Sept. 1, 1992 - Inspection 50-309/92-15

Subject: Inspection 92-15: Anticipated Transient Without Scram (ATWS) Rule Implementation Inspection


Gentlemen:

The NRC noted in its Findings in Reference (b) that one ATWS wiring termination was incorrectly labeled. Maine Yankee committed during the exit meeting to perform a recheck of all the ATWS termination labeling. Maine Yankee committed to complete the inspection of accessible portions by mid-September 1992.

Maine Yankee Engineering review of the task concluded that the work on the wire terminations should be performed during a plant shutdown to avoid inadvertent operation challenging plant safety systems. Maine Yankee is committed to completing this task during the next refueling shutdown, tentatively scheduled to start in late August, 1993.

Please contact us should you have any questions regarding this matter.

Very truly yours,



James R. Hebert, Acting Manager
Licensing & Engineering Support Department

EBB/jag

c: Mr. Thomas T. Martin
Mr. Charles S. Marschall
Mr. E. H. Trottier
Mr. Patrick J. Dostie

9211100072 921104
PDR ADOCK 05000309
G PDR

L:\jrh\ltrs\jrh92150.1tr

TEO1 1/0