NRC FORM 591 PART 1 U.S. NUCLEAR REGULATORY COMMISSION (7-91)SAFETY INSPECTION 10 CFR 2.201 Inspection conducted at Red Wing, Minnesota Page 1 of 1 1. LICENSEE 2. REGIONAL OFFICE ADM Malting Division - Fleischmann REGION III Malting Company U S NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD P. O. Box 340470 LISLE IL 60532-4351 Milwaukee, Wisconsin 53234-0470 3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S) 5. DATE OF INSPECTION August 22, 1996 030-31776/030-31485 48-26208-01 LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows: X Within the scope of this inspection, no violations were observed. 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a NOTICE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11. was not properly posted to indicate the presence of a __ 10 CFR 20.203(b),(c),(d),(e) or 34.42. B. of sealed sources were not performed at the proper frequencies. 10 CFR _______ or License Condition Number _____ C. Records of were not properly maintained. 10 CFR _____ or License Condition Number ____ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11. E. Reports or notification of were not made in accordance with 10 CFR ______ or License Condition Number _____ I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC SIGNATURE - LICENSEE DATE 9609050035 960827 PDR ADOCK 03031776

NRC FORM 591 Part 1 (7-91)