



Northeast  
Utilities System

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company  
P.O. Box 270  
Hartford, CT 06141-0270  
(203) 665-5000

AUG 31 1996

Docket No. 50-213  
B15836

Re: 10CFR50.71(e)

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Haddam Neck Plant  
Supplement to Revision 9 to the Updated Final Safety Analysis Report

Connecticut Yankee Atomic Power Company (CYAPCO) hereby submits, as Attachment 1, a Supplement to Revision 9 to the Updated Final Safety Analysis Report (UFSAR) in the form of replacement pages, as required. This supplement fulfills the commitment contained in the letter dated July 1, 1996,<sup>(1)</sup> which transmitted Revision 9. Pursuant to 10CFR50.71(e)(2)(i), I certify that, this supplement, along with our July 1, 1996 submittal accurately presents changes that are necessary to reflect information and analyses submitted to the Commission or prepared pursuant to Commission requirements, as of December 1, 1995.

This supplement contains Section 13.1 - Organizational Structure, and reflects organizational changes submitted to the NRC in letter dated June 10, 1996,<sup>(2)</sup> which transmitted Revision 19 of the NU Quality Assurance Program (NUQAP). This action closes commitment B15762-1 contained in the July 1, 1996 letter.

CYAPCO made a second commitment in the letter dated July 1, 1996, to provide a change to Section 6.3.2.8, "Manual Actions," to document the time specified for the transition to two-path recirculation following a Loss-of-Coolant Accident. This change was to reflect the analysis

- 
- (1) T. C. Feigenbaum letter to U. S. Nuclear Regulatory Commission, "Revision 9 to the Updated Final Safety Analysis Report", dated July 1, 1996.
  - (2) T. C. Feigenbaum letter to U. S. Nuclear Regulatory Commission, "Annual Reporting of Changes to the Quality Assurance Program Proposed Revision 19 to the Northeast Utilities Quality Assurance Program Topical Report", dated June 10, 1996.

9609110266 960831  
PDR ADOCK 05000213  
K PDR

AD53 11

supporting continuation of Cycle 19. Since CYAPCO elected to enter the refueling outage at an earlier date, this change was not implemented and therefore a UFSAR change was not made. This action closes commitment B15762-2 contained in the July 1, 1996 letter.

Pursuant to 10CFR50.71(e) and 10CFR50.4(b)(6), this transmittal consists of one original and ten copies. As stipulated in 10CFR50.71(e)(2)(ii): "This submittal shall include an identification of changes made under the provisions of Section 50.59, but not previously submitted to the Commission." Pursuant to Section 50.59(b) and Technical Specification Section 6.9.1.4, such information is routinely submitted to the NRC as part of our annual reports, and is not included in this submittal. The most recent annual report was submitted on February 27, 1996, for the period January 1, 1995, through December 31, 1995.


There are no commitments contained within this letter. Statements made within this letter are for information only. If you have any questions, please contact Mr. E. P. Perkins, Jr. at (860) 267-3938.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY

FOR: T. C. Feigenbaum  
Executive Vice President and  
Chief Nuclear Officer

BY:

  
E. A. DeBarba  
Vice President

cc: H. J. Miller, Region I Administrator  
S. Dembek, NRC Project Manager, Haddam Neck Plant  
W. J. Raymond, Senior Resident Inspector, Haddam Neck Plant