

Duke Power Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MG01VP)
Huntersville, NC 28078-8685

T. C. McMEEKIN
Vice President
(704)875-4800
(704)875-4809 Fax



DUKE POWER

September 4, 1996


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station
Units 1 and 2
Docket Nos. 50-369, 370
Preliminary Accident Sequence Precursor Analysis
Request for Additional Information

On 8/5/95, the NRC issued the 'Preliminary Accident Sequence Precursor (ASP) Analysis of the Failure of the Turbochargers Associated With The Emergency Diesel Generators McGuire Nuclear Station, Units 1 and 2'. The 8/5/95 letter requested comments on the preliminary ASP review within thirty days.

Per our telecon of August 28, 1996, please find attached additional technical information related to the June, 1995 failures of the McGuire EDG turbochargers. Following the completion of reanalysis of the preliminary ASP by ORNL using the attached information, McGuire plans to provide additional comments as requested per your August 5, 1996 letter.

Additional questions or problems should be directed to Kay Crane, McGuire Regulatory Compliance at (704) 875-4306.


T. C. McMeekin, Vice President
McGuire Nuclear Station

cc: Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

S. D. Ebnetter, Regional Administrator
Region II
U. S. Nuclear Regulatory Commission
101 Marietta St. NW, Suite 2900
Atlanta, GA 30323

Mr. Scott Shaeffer
Senior Resident Inspector
McGuire Nuclear Station

9609170542 960904
PDR ADDCK 05000369
P PDR