February 8, 1973

Docket No. 50-263

Mr. Harold G. Mangelsdorf Chairman, Advisory Committee on Reactor Safeguards U. S. Atomic Energy Commission Washington, D. C. 20545

Dear Mr. Mangelsdorf:

Sixteen (16) copies of the following are transmitted for the

information: Committee's

> Letter from Northern States Power Company dated January 18, 1973, furnishing information regarding the Monticello rod drop accident analysis.

> Letter from Northern States Power Company dated January 22, 1973, furnishing additional information regarding the main steam isolation valve performance at Monticello.

Letter from Northern States Power Company dated January 23, 1973, reporting a low condenser vacuum scram switch disphragm leak which occurred at Monticello.

Sincerely,

Distribution Docket File Branch Reading

Donald J. Akovholt Assistant Director for Operating Reactors Directorate of Licensing

Enclosures: As stated

L:ORB /#2 OFFICE . SURNAME & DATE Form AlC-818 Rev. 9-53) AECM 0240 GPO 643-16-81465-1 445-678

9212080395 730200