



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000
January 4, 1980

2-010-2

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-358
License No. NPP-6
Licensee Event Report Nos.
79-094/03L-0, 79-095/03L-0
and 79-096/03L-0
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached are the subject reports concerning a low pressurizer pressure trip (79-094/03L-0), an inoperable DC bus train (79-095/03L-0) and the inoperability of a core protection calculator channel (79-096/03L-0).

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:MAS:skm

Attachments

cc: Mr. Norman M. Haller, Director
Office of Management and
Program Analysis
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Mr. Victor Stello, Jr., Director
Office of Inspection and
Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Mr. W. D. Johnson
U. S. Nuclear Regulatory Comm.
P. O. Box 2090
Russellville, AR 72801

90022297

8001110 587