



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775
AREA CODE 504 835-6094 846-6851

December 4, 1992
RBG- 37795
File Nos. G9.5, 224.600

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

River Bend Station - Unit 1
Docket No. 50-458


Gulf States Utilities Company (GSU) recently completed an extensive refueling outage at River Bend Station. From March 12, 1992, to September 8, 1992, a number of preventive maintenance items, plant modifications, and repairs were completed, many of which were subject to the requirements of Section XI of the ASME Boiler and Pressure Vessel Code and Addenda. Two major projects were the replacement of the reactor pressure vessel (RPV) N4A feedwater nozzle and the reactor water cleanup (RWCU) ringheader. Both entailed a great deal of welding, support replacement and valve replacement. Per Article IWA-6230, "Summary Report Submittal," of ASME Section XI, within 90 days of the completion of the inservice inspection conducted during the refueling outage, inservice inspection summary reports for Class 1 and Class 2 pressure retaining components and their supports must be submitted to the regulatory authorities having jurisdiction at the plant site, in this case the Nuclear Regulatory Commission. Due to the extensive amount of inservice inspection information, GSU will require an extension until January 15, 1993, to complete the Summary Report. This extension will provide time for an accurate and thoroughly reviewed single submittal of the Summary Report with all the information required per IWA-6220, "Preparation," rather than necessitating a supplementary submittal.

140031
9212150153 921204
FOR ADOCK 05000458
P PDR


A047 1/0

If you have any questions or require additional information, please contact Mr. L.L. Dietrich of my staff at (504) 381-4866.

Sincerely,



W.H. Odell
Manager - Oversight
River Bend Nuclear Group



LAE/LLD/ICM/DLA

cc: U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Resident Inspector
P.O. Box 1051
St. Francisville, LA 70775

Mr. E. Baker
U.S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852