

THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

MURRAY R. EDELMAN VICE PRESIDENT NUCLEAR

> June 7, 1985 PY-CEI/OIE-0061 L

Mr. James. G. Keppler Director, Region III Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Glen Ellyn, 1L. 60137

> Perry Nuclear Power Plant Docket No. 50-440; 50-441 I. E. Bulletin 83-07; 83-07 Supplements 1 and 2

Dear Mr. Keppler:

The following information is provided to supplement and clarify our response to I.E. Bulletin 83-07 and Supplement 1 and 2 describing apparently fradulent products sold by Ray Miller, Inc.

Previous letters dated March 15, 1984 (PY-CEI/OIE-0006 L) and January 15, 1985 (PY-CEI/OIE-0024 L), informed the NRC of investigative efforts to determine whether any Ray Miller, Inc. products had been received at Perry Nuclear Power Plant (PNPP) for use in safety-related applications. As a result, it was reported that PNPP did not receive any fraudulent products from Ray Miller Inc. for use in safety-related applications. However, a single non-safety application of Ray Miller products was noted in both letters. This application involved the "potential" use of Ray Miller material in the strainer assemblies.

This previously identified non-safety application applied to the Emergency Service Water and Emergency Service Water Screen Wash Strainers. Initial evaluation of the backwash assembly of the R. P. Adams Strainers determined that the strainers were classified as "Non-Active" components, so that automatic operation was not required since the strainers could be manually backwashed, if necessary. The operation of the backwash assembly was therefore considered non-safety related. Subsequent communication with Gilbert/Commonwealth Inc., our Architect/Engineer, has shown that the backwash function, although a manual operation, is still a safety-related function.

850614039 ADOC

JUN 1 0 1985

J. G. Keppler

June 7, 1985 PY-CEI/OIE-0061 L

The NRC was notified by the Cleveland Electric Illuminating Company on May 8, 1985 that we had initiated Deviation Analysis Report (DAR) 240 to evaluate the significance of this condition. When our evaluation is complete, and any required corrective actions have been identified, we will inform you of the results.

If there are any questions, please feel free to call.

Very truly yours,

Caplan

Murray R. Edelman Vice President Nuclear Group

MRE:njc

cc: Jay Silberg, Esq. John Stefano (2) J. Grobe