

Docket No. 50-288

JUN 11 1985

Reed College
3203 S. E. Woodstock Street
Portland, Oregon 97202

Attention: Dr. Michael Kay
Reactor Director

Gentlemen:

This letter refers to an unannounced, routine, safeguards inspection of your activities authorized by NRC License No. R-112 conducted by Mr. L. R. Norderhaug of this office on May 22 and 23, 1985. It also refers to the discussions of our preliminary inspection findings held by the inspector with Dr. Marshall Cronyn and other members of the Reed College organization on May 23, 1985 and a subsequent conversation with you on June 5, 1985.

Areas examined during this inspection included activities related to physical protection as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility and other personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of the findings of your safeguards and security measures are exempt from public disclosure; therefore, the enclosures to this letter will not be placed in the Public Document Room and will receive limited distribution.

Should you have any questions concerning this letter, we would be pleased to discuss them with you.

Sincerely,

Original signed

James L. Montgomery, Chief
Nuclear Material Safety and
Safeguards Branch

Enclosure:
Inspection Report No. 50-288/85-02 (IE-V-693)

cc w/enclosure:
Dr. M. Cronyn, Reed College

bcc w/o enclosure: pink/green; LFMB; State of Oregon

bcc w/enclosure: docket file; Mr. Martin; RSB/Document Control Desk (RIDS)

RV *RV*
Norderhaug/dot
6/10/85

MCS
Schuster
6/10/85

Jim
Montgomery
6/10/85

8506170489 850611
PDR ADOCK 05000288
G PDR

IED2