



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

JMB

June 13, 1985

Mr. James G. Keppler
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: Braidwood Station Units 1 and 2
10 CFR 50.55(e) No. 84-01 Final Report
L. K. Comstock Document Review
NRC Docket Nos. 50-456/457

- References (a): E. D. Swartz letter to J. G. Keppler dated
March 2, 1984
- (b): E. D. Swartz letter to J. G. Keppler dated
May 21, 1984
- (c): E. D. Swartz letter to J. G. Keppler dated
July 19, 1984
- (d): D. H. Smith letter to J. G. Keppler dated
December 3, 1984
- (e): D. H. Smith letter to J. G. Keppler dated
March 21, 1985

Dear Mr. Keppler:

References (a) thru (e) provided information concerning a deficiency reportable pursuant to 10 CFR 50.55(e) regarding L. K. Comstock Document Review at our Braidwood Station. The purpose of this letter is to provide an updated status of the corrective actions being taken to resolve this issue. This letter is considered to be a Final Report.

Since the submittal of Reference (e), the administrative hold which CECO PCD placed on the L. K. Comstock Document Review Program has been lifted. This action was taken based on the review and approval of L. K. Comstock procedure 4.13.1.1, Turnover Document Review. This procedure incorporates corrective actions which were deemed necessary to lift the administrative hold and ensure a thorough document review.

The program encompasses L. K. Comstock inspection records currently filed in the vault and any new records which will be generated.

8506260477 850613
PDR ADOCK 05000456
B PDR

JUN 17 1985


IT 2710

To date no significant discrepancies have been identified which require extensive rework.

The document review portion of this program is scheduled for completion in December 1985 for records associated with Unit 1 and common areas, and March, 1986 for Unit 2 records. Final correction and completion of deficiencies identified during this review will be dependent on the total number found and the extent to which they are deficient. Commonwealth Edison Company considers this to be the final report for this program.

Please address any questions that you or your staff may have concerning this matter to this office.

Very truly yours,



A. D. Miosi
Nuclear Licensing Administrator

/klj
cc: NRC Resident Inspector - Braidwood

Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

261K