



NORTHERN STATES POWER COMPANY

Monticello Nuclear Generating Plant  
Monticello, Minnesota 55902

September 19, 1975

Mr. J. G. Keppler, Director  
Region III  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Bllyn, Illinois 60137

Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-253 License No. DPR-22

On September 19, 1975, during local leak rate testing of MSIV's 2-80A and 2-86A, it was found that the combined leakage of these valves exceeded the acceptance criteria as listed in Technical Specification 4.7.A.2(f)(2)(c). It was also found that the combined leakage of MSIV's 2-80C and 2-86C exceeded this acceptance criteria. Further investigation of this occurrence is continuing.

Yours very truly,

*C. E. Larson*

C. E. Larson  
Plant Manager

CBL/rmm

cc: R.S. Boyd  
G. Charnoff  
Minnesota Pollution Control Agency  
Attn: J.W. Ferman  
Rile

Copies sent by telecopier to Keppler and Boyd

9211230471 750919  
PDR ADOCK 05000263  
S PDR

9/19  
Rec'd 3:06 Dec